

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

19-Feb-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB8054 L

1 pc	Bootlid emblem	\$ 27.00	x
1 pc	Bootlid CRDi	\$ 29.00	x
1 pc	Boot lid lower garnish	\$ 290.00	x
1 pc	Rear bumper	\$ 696.00	de
1 pc	Rear bumper lower cover	\$ 206.00	de
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$ 58.00	x
1 pc	Rear bumper inner sponge	\$ 114.00	x
1 pc	Rear bumper reinforcement	\$ 607.00	x
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$ 106.00	x
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$ 36.00	x
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$ 36.00	x
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$ 92.00	x
		\$ 2,297.00	
		\$ 229.70	
		\$ 2,067.30	

Tarifika 97495749
up 24/2/2020 1420
2 days w/s Resurvey after repair
Tarifika ekkentoum

Less 10%

696
10% - 626.40

S/NETT

1 set	Rear bumper clips	\$ 48.00	30
1 set	Bootlid lower garnish clips	\$ 60.00	xnn
1 set	Bootlid stickers	\$ 100.00	xnn
1 set	Reverse sensor	\$ 280.00	200 xnn
1 pc	Rear bumper protector	\$ 80.00	xnn
	Sundry	\$ 50.00	xnn 30
To dismantle / replace reverse sensor to new bumper and reset to the same		\$ 120.00	30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00	xnn
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$ 800.00	200
To putty and spray painting on bootlid lower garnish, rear bumper, end panel, boot lid		\$ 800.00	200
To apply rustproofing on the repaired and replaced panels.		\$ 120.00	xnn 430
		\$ 4,705.30	

1086.40

1/5/850 02 days

#