

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 06 Apr 2021

Preliminary Advice

Insured Vehicle No : GBH7578M

TP Vehicle No : SMC9854Z

Make : HONDA VEZEL

Date of Inspection : 19/02/2021

Inspection At : JWG INTERNATIONAL PTE LTD (HQ)

BLK 10, ANG MO KIO IND PARK 2A,, #03-08 AMK AUTOPOINT
SINGAPORE 568047

Accident Date : 18/02/2021

Assignment Date : 22/02/2021

Est. Duration of Repair : 2

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,278.81
Revised Amount	:S\$	500.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	500.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (x) The above survey was conducted on a 'without prejudice' basis.