MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

Tel: 6748 4422 / 6745 4422 Fax: 6747- 6720 REG NO 200501102H

4 Shen SGX (Singap Hot line	NSURANCE (S) PTE LTD Iton Way # 21 - 01 Centre 2 ore 068807 e: 6827 - 7660 C225- 7402 (CLAIM)	DATE VEH NO MODEL D O A YR REF	: 12.0 : GBH : Toyo : 08.0	tation 3.2021 16801A ota Dyna 1.2021 4634M
Attn:	Motor Claim Dept (pls arrange vehicle survey & check liability)			
RE:	ESTIMATE FOR ACCIDENT REPAIR GBH6801A (TOYOTA DYNA)			
<u>Item</u>	Description	Qty		_Amt
NO	LIST ITEMS			
1 2 3 4 5 6	Front Bumper Bracket - LH Wen Head Lamp - LH Could Head Lamp Lower Rubber - LH Wen Front Step Garnish - LH Wen Front Door - LH Distorted 32 Less 25% S/NET ITEMS Head Lamp Lower Rubber Clips Front LH Door Company Address Sticker New Front LH Door Advertisement Sticker New	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$ \$ \$ \$	589.50 253.30 975.10 47.20 276.00 1,650.40 3,791.50 (947.88) 2,843.63 10.00 30.00 300.00 200
			\$	340.00
	Total parts		\$	3,183.63
	LABOUR CHARGE			
1	To knocking & pull out Front LH portion & renew above	ve parts	\$	600.00 HOO
2	To putty and spray up paint works		\$	600.00 HOD
3	To check wiring system	910	\$	50,00 30
4	To transfer door fittings		\$	150.00 80

RE: ESTIMATE FOR ACCIDENT REPAIR GBH6801A (TOYOTA DYNA)

\$ 1,400.00

GRAND TOTAL

\$ 4,583.63

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 355125 CP/P) 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: