

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 429P

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER | MTG CRACKED | 985.10 | 985.10 |
| 1 | REAR BUMPER REINFORCEMENT | BENT | 483.20 | 483.20 |
| 2 | REAR BUMPER REFLECTOR GARNISH @\$125.60 | O/S MTG DISTORTED / N/S SERVICEABLE | 251.20 | 125.60 |
| 1 | REAR BUMPER CENTER GARNISH | SERVICEABLE | 95.60 | - |
| 1 | REAR LOWER BUMPER | DENTED | 455.60 | 455.60 |
| 1 | REAR BUMPER TOW COVER | DENTED | 55.10 | 55.10 |
| 2 | REAR BUMPER SIDE RETAINER @\$75.10 | SERVICEABLE | 150.20 | - |
| 1 | REAR ANTENNA | SERVICEABLE | 175.20 | - |
| 2 | REAR FENDER ARCH GARNISH @\$165.20 | SERVICEABLE | 330.40 | - |
| 1 | REAR END PANEL | TO REPAIR SEE LABOUR | 725.70 | - |
| 1 | REAR END PANEL INNER GARNISH | SERVICEABLE | 402.10 | - |
| | LESS 25% DISCOUNT | | -1,027.35 | -526.15 |
| | | | 3,082.05 | 1,578.45 |
| | SPECIAL NETT ITEMS | | | |
| 15 | REAR BUMPER CLIP @\$2.00 (SN) | NECESSARY | 30.00 | 30.00 |
| 1 | REAR REVERSE SENSOR (SN) | SHORTED | 200.00 | 200.00 |
| | | | 230.00 | 230.00 |
| | <u>LABOUR</u> | | | |
| | REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF REAR END PANEL. | | 800.00 | 200.00 |
| | TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION. | | 800.00 | 200.00 |
| | CHECK AND RECONNECT WIRING. | | 40.00 | 15.00 |
| | TO ANTI-RUST PROOFING. | NOT NECESSARY | 100.00 | - |
| | | | 1,740.00 | 415.00 |
| | GRAND TOTAL | | 5,052.05 | 2,223.45 |

Report Ref No. CS/SMO21002383/Kvd3q2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 1,750.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | |

Report Ref No. CS/SMO21002383/Kvd3q2

KONG SENG CHEONG

Licensed Appraiser