



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21002385/GUqd3n2	
			Date: 16/06/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 712T		Veh. Inspected	SLR 8505X
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2100551/RUC		Excess (\$)	0.00
Assign From	GRACE TEO		Assign Date	19/02/2021
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT 1.3G		c.c	1339
Engine No.	HIDDEN		Year of Reg.	2008
Chassis No.	GE61060825		Colour	PINK
Odometer	216644 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R14	PIRELLI	6 mm	
L/H Front Tyre	185/65 R14	PIRELLI	6 mm	
R/H Rear Tyre	185/65 R14	PIRELLI	6 mm	
L/H Rear Tyre	185/65 R14	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/02/2021		Inspection Date	19/02/2021
Survey held at	15 KAKI BUKIT ROAD 4 # 01-05/53			
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	