



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile               |  |  |                           |                      |
|---|--|--|---------------------------|----------------------|
| TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO STREET 63SINGAPORE<br>569111 |  |  | Ref: CS/TP21002387/Kqd3e2 |                      |
|   |  |  | Date: 22/03/2021          |                      |
|   |  |  | Code: TP378               |                      |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                               |  |  |                           |                      |
|   | Insured Veh.   | Veh. Inspected   | SHC 5951L                 |                      |
|   | Policy No.   | Coverage (\$)  | 0.00                      |                      |
|   | Claim No.  | Excess (\$)  | 0.00                      |                      |
|   | Assign From  | Assign Date  | 15/02/2021                |                      |
| <b>2. Vehicle Particulars &amp; Condition</b>                                   |  |  |                           |                      |
|   | Make & Model   | RENAULT LATITUDE (A)   | c.c                       | 1995                 |
|   | Engine No.   | HIDDEN   | Year of Reg.              | 2014                 |
|   | Chassis No.  | VF1ABL15AUC280987  | Colour                    | METALLIC WHITE / RED |
|   | Odometer   | 606516 KM  | Steering                  | IN ORDER             |
|   | Brakes   | IN ORDER   | Modification              | NIL                  |
|   | General  | GOOD   |                           |                      |
| <b>3. Conditions of Tyres</b>   |  |  |                           |                      |
|   |  | Size   | Make                      | Balance              |
|   | R/H Front Tyre   | 215/60 R16   | SAILUN                    | 8 mm                 |
|   | L/H Front Tyre   | 215/60 R16   | SAILUN                    | 8 mm                 |
|   | R/H Rear Tyre  | 215/60 R16   | SAILUN                    | 8 mm                 |
|   | L/H Rear Tyre  | 215/60 R16   | SAILUN                    | 8 mm                 |
| <b>4. Description of Damages</b>  |  |  |                           |                      |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br>DAMAGES SEE DETAILS.  |  |                           |                      |
| <b>5. General Information</b>   |  |  |                           |                      |
|   | Accident Date  | 07/02/2021   | Inspection Date           | 15/02/2021           |
|   | Survey held at   | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                           |                      |
| <b>5a. Remarks</b>  |  |  |                           |                      |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                           |                      |
| <b>5b. Estimate Days of Repair</b>  |  |  |                           |                      |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | 2 Working Days            |                      |