



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2205528

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 08/09/2022
Reference CC6/CTI21002389/Aea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMR 4045X
Insured Veh. SMU 6723T
Claim No. SNM21D200934/C02
Policy No. DMHCSNW000012221000
Accident Date 17/02/2021
Inspection Date 18/02/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI21002389/Aea3q2	
			Date: 08/09/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMU 6723T	Veh. Inspected	SMR 4045X	
Policy No.	DMHCSNW000012221000	Coverage (\$)	0.00	
Claim No.	SNM21D200934/C02	Excess (\$)	0.00	
Assign From		Assign Date	18/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	GB71085915	Colour	WHITE	
Odometer	84367 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/60 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/60 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/60 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/02/2021	Inspection Date	18/02/2021	
Survey held at	GREEN FOREST AUTOMOBILE PTE LTD 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 4045X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	DISTORTED	1,350.00	1,208.00
2	REAR BOOT LID HINGES @\$115.00	NOT NECESSARY	230.00	-
1	REAR BOOT LID RUBBER	CUT	205.00	205.00
1	?REAR BOOT LID INNER TRIM	CRACKED	680.00	345.00
1	BOOT LID INNER LOCK	DAMAGED	203.10	203.10
8	REAR BOOT LID CENTER GARNISH CLIPS @\$5.50	NOT NECESSARY	44.00	-
1	REAR BOOT LID CENTRE GARNISH /MOULDING	NOT NECESSARY	285.10	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	60.00	60.00
1	REAR BOOT LID FREED LOGO	NECESSARY	40.00	40.00
1	REAR BOOT LID HYBRID LOGO	NECESSARY	48.00	48.00
2	REAR BOOT LID SIDE REFLECTOR @\$375.00	NOT NECESSARY	750.00	-
1	REAR BOOT LID WINDSCREEN SEAL	NECESSARY	138.20	138.20
2	REAR NUMBER PLATE LAMP @\$58.00	NOT NECESSARY	116.00	-
1	REAR NUMBER PLATE	NOT NECESSARY	50.00	-
2	REAR BUMPER SIDE REFLECTOR @\$65.00	NOT NECESSARY	130.00	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	64.00	-
1	REAR BUMPER	DEFORMED	1,358.00	829.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	458.00	-
2	REAR BUMPER SIDE BRACKET @\$85.20	NOT NECESSARY	170.40	-
2	REAR BUMPER SIDE RETAINER @\$105.20	NECESSARY	210.40	90.00
8	REAR BUMPER CLIPS @\$5.00	NECESSARY	40.00	40.00
2	REAR TAIL LAMP @\$580.00	NOT NECESSARY	1,160.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	740.00	-
1	REAR END PANEL TOP GARNISH	DEFORMED	284.00	284.00
	LESS 20% DISCOUNT		-	-698.06
			8,814.20	2,792.24
	<u>LABOUR</u>			
	REMOVE /REFIX REAR WINDSCREEN .		120.00	120.00
	GUM.		50.00	50.00
	REMOVE/REFIX REAR CUSHION .		120.00	40.00

Report Ref No. CC6/CTI21002389/Aea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.		120.00	40.00
	TO CHECK WIRING SYSTEM.		60.00	30.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,000.00	600.00
	SPRAY PAINTING CHARGES.		1,000.00	600.00
			2,470.00	1,480.00
GRAND TOTAL			11,284.20	4,272.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CC6/CTI21002389/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMR 4045X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMR 4045X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

