

8 Kaki Bukit Ave 4 #08-45/46 Premier@ Kaki Bukit S415875
Tel: 6702 1555 Fax: 6702 1444 ROC No. : 201500047H

ESTIMATE

TO : AIG Insurance	DATE : 16-Feb-2021
ATTENTION : MOTOR CLAIM DEPARTMENT	JOB TYPE : THIRD PARTY CLAIM
VEHICLE DETAILS	
VEHICLE NO. : SMW2598D	DATE : 7-Feb-2021
MAKE / MODEL : MG HS	TIME : 13:33 hr
CHASSIS NO. : LSJA24U94LN035256	
OWNER INSURANCE : LIBERTY INSURANCE	
POLICY NO. : SD20V14791/VPC/ROO	
PERSON INCHARGE : Falcoe T: 6702 1555 F: 6702 1444 falcoelee@skauto.com.sg	

CLAIM DETAIL : LIST PRICE (\$\$)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Rear Bumper <i>del</i>	1	\$ 750.00	\$ 750.00
2	Rear Bumper Lower Garnish <i>del</i>	1	\$ 497.00	\$ 497.00
3	Rear Bumper Lower Lid <i>del</i>	1	\$ 278.00	\$ 278.00
4	Rear Bumper Towing Cover <i>new</i>	1	\$ 33.00	\$ 33.00
5	Rear Bumper Reflector LH / RH <i>new</i>	2	\$ 48.00	\$ 96.00
6	Rear Bumper Reinforcement <i>3 set Dented</i>	1	\$ 688.00	\$ 688.00
7	Rear Bumper Reinforcement Bracket LH / RH <i>new</i>	2	\$ 158.00	\$ 316.00
8	Rear End Panel <i>new</i>	1	\$ 886.00	\$ 886.00
9	Tailgate Lock <i>new</i>	1	\$ 197.00	\$ 197.00
10	Tailgate Lock Cover <i>new</i>	1	\$ 18.00	\$ 18.00
11	Rear Exhaust <i>new</i>	1	\$ 2,070.00	\$ 2,070.00
12	Rear Exhaust Mounting <i>new</i>	4	\$ 31.00	\$ 124.00
13	Rear Parking Sensor <i>2 pieces dented</i>	4	\$ 135.00	\$ 540.00
14	Rear Parking Sensor Bracket <i>new 2 pieces</i>	4	\$ 30.50	\$ 122.00

TOTAL PRICE : \$ 6,615.00

LIST LESS 10% : \$ 661.50

SUB TOTAL PRICE : \$ 5,953.50

2544

2289.60

CLAIM DETAIL : PARTS S/NETT

S/N	DESCRIPTION	QTY	UNIT S/N PRICE	TOTAL S/N PRICE
1	Rear Bumper Clips <i>new</i>	1	\$ 50.00	\$ 50.00 30
2	Rear Bumper Lower Lid Clips <i>new</i>	1	\$ 50.00	\$ 50.00 20
3	Rear Bumper Adhesive Protector Guard <i>new</i>	1	\$ 240.00	\$ 240.00 180
			S/N TOTAL PRICE: \$	<u>340.00</u>

230

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	DESCRIPTION	PRICE	ADJUST
1	Labour charge to panel beat & straighten affected panels and replace above mentioned parts	\$ 560.00	250.
2	To spray paint Rear Bumper, Reverse Parking Sensor & Rear Bumper Undertray	\$ 560.00	200.
3	To perform rear electrical wiring checks and functionality checks	\$ 160.00	30.
4	Installation and calibration/setting for reverse sensor	\$ 160.00	50.

LABOUR TOTAL PRICE: \$ 1,440.00

530

ESTIMATE REPORT

TOTAL PARTS PRICE : \$	6,293.50
TOTAL LABOUR PRICE : \$	1,440.00
TOTAL AMOUNT : \$	<u>7,733.50</u>

total: 3049.60

c/s: 2.4k.

02 Days

APPROVED DETAILS

NO.OF REPAIR DAYS :

P & P OR LUMPSUM :

SURVEYED BY :

CONTACT NUMBER :

E-MAIL :

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: