



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/CHIN SWEE KHONG
	Reg No/Reg Date	SMP1799J / 13/09/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0602003
	Engine No	4J11BJ0870
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	W01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/02/2021/ 12:35	QUD	247 / DonBong	63067

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW LHF ¹ DOOR , LHR ¹ DOOR & LHR ³ FENDER REPAIR & RE-ALIGN RR BUMPER , LH CENTRE PILLAR & LH ROCKER PNL	4.5 X 450			2925 3150.00
E PNT98000 RESPRAY LHF ¹ DOOR , LHR ¹ DOOR , LHR ¹ FENDER , LH CENTRE PILLAR , LH ROCKER PNL & RR BUMPER	3 X 350			1050 2100.00
E PNT88000 REMOVE & REFIT LHF DOOR COMPONENT				120.00 ✓
E PNT88000 REMOVE & REFIT LHR DOOR COMPONENT				120.00 ✓
E PNT88000 REMOVE & REFIT RR FLR BOARD , TRIM CARPET & SEA (photo)				30.00 ✓
M SUNDRY RENEW LHR SPORT & TYRE				480.00 ✓
M SUNDRY SUPPLY LHR TYRE-TOYO A24 225/55R18				30.00 ✓
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				120.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				120.00 ✓
E PNT88000 REMOVE & REFIT LHR FENDER QTR GLASS				80.00 ✓
M SUNDRY SUPPLY QTR GLASS SEALANT				100.00 ✓
M SUNDRY INSTALL QTR GLASS SOLAR FILM				80.00 ✓
E PNT88000 REMOVE & REFIT REVERSE SENSOR				40 120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

CYCLE & CARRIAGE

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892		Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model Colour/Trim	/CHIN SWEE KHONG / 13/09/201 / 0 GF7W0602003 4J11BJ0870 MIT/19MY OUTLANDER 2.0 STYLE(994) W01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
KAX00008	Credit	19/02/2021/ 12:35	QUD	247 / DonBong	63067				80.00
Description of Goods / Services									
M	SUNDRY								20.00
	SUPPLY BODY PNL SEALANT								20.00
M	SUNDRY								752.29
	Sundries					1.00	982	977.00 23.00	100.10
M	PANEL ASSY,FR DOOR,LH	DD ? X NM				1.00	130.00	23.00	129.36
M	MLDG,F/DR WDO BELT LINE,LH	REC				1.00	190	168.00 23.00	32.34
M	GARNISH,FR DOOR,LH	REC				1.00	42.00	23.00	247.94
M	TAPE,FR DOOR SASH,LH	REC				1.00	322.00	23.00	661.43
M	LATCH,FR DOOR,LH	X NM				1.00	864	859.00 23.00	95.48
M	PANEL ASSY,RR DOOR,LH	DD ? X NM				1.00	124.00	23.00	25.41
M	MLDG,R/DR WDO BELT LINE,LH	X NM				1.00	33.00	23.00	33.11
M	W/STRIP,R/DR OPN,LWR OTR L	X NM				1.00	43.00	23.00	33.11
M	HINGE,RR DOOR,UPR LH	X NM				1.00	43.00	23.00	107.03
M	HINGE,RR DOOR,LWR LH	X NM				1.00	139.00	23.00	150.15
M	W/STRIP,R/DR OPNG,OTR LH	X NM				1.00	195.00	23.00	111.65
M	W/STRIP,R/DR OPNG,INR LH	X NM				1.00	164	145.00 23.00	32.34
M	GARNISH,RR DOOR,LH	REC				1.00	42.00	23.00	32.34
M	TAPE,RR DOOR SASH	REC				1.00	42.00	23.00	247.17
M	TAPE,RR DOOR SASH	REC				1.00	321.00	23.00	15.40
M	LATCH,RR DOOR,LH	X NM				1.00	20.00	23.00	24.64
M	STRIKER,FR DOOR LATCH	X NM				1.00	32.00	23.00	994.07
M	CHECK,RR DOOR	X NM				1.00	1298	1291.00 23.00	123.20
M	PANEL,QTR,OTR LH	DD				1.00	160.00	23.00	81.62
M	MOULDING,RR WHEEL ARCH,LH	CUT				1.00	106.00	23.00	549.01
M	MOULDING,RR BUMPER,LH	CUT				1.00	713.00	23.00	749.98
M	GLASS,QTR WINDOW,LH	REC				1.00	974.00	23.00	1243.20
M	WHEEL,DISC LHR	CUT				1.00	1554.00	20.00	
M	BODY KIT, OUTLANDER	CUT							

SURVEYOR NAME : Steve (LKK)
 SURVEYOR SIGNATURE : 92/2/21, 3.00pm
 DATE : DD-MM-YY

Confirm & accepted by	REMARKS :	Nett	13,562.37
Auto Consultant's hence notify Repairer of the following: resurvey before/after spray painting display damaged part(s) during resurvey parts prices are subject to confirmation and part survey is on a "without prejudice" basis	<u>EXCESS - ?</u> <u>P/P, R, BL BY</u> <u>10 days</u>	7% GST on	949.37
Authorized signatory and company stamp		Total Payable	14,511.74

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.