

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SLJ1789G

Accident Date : 18/2/2021

Location : BEDOK NORTH AVE 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____
Model: MITSUBISHI LANCER
(30/11/2016)

3P: GBK5679C (III)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper ✓ DE	680.00	-	-
2	8 pcs	Rear bumper clips ✓ NEC	-	24.00	-
3	1 pc	Rear bumpe tape ✓ NEC	-	20.00	-
4	1 pc	Rear n/s bumper reflector X NN	80.00	-	-
5	1 pc	Rear end panel X NN	581.60	-	-
6	2 pcs	Rear reverse sensor X NN	-	280.00	-
7	1 pc	Rear enforcement X Repair	320.60		
Sub-Total:			1,662.20	324.00	0.00
			10%	0%	0%
After Less %:			1,495.98	324.00	0.00
Labour			612	44	
1		To remove & replace damaged parts.		800.00	300
2		To spray painting		500.00	250
3		To check wiring		50.00	X NN
4		To re-seal anti-rust		80.00	X NN
5		To remove & replace rear reverse sensor		40.00	✓
Sub-Total:				1,470.00	
Total:				3,289.98	
After Less 20%:				2,631.98	

Chan San Choon
Director

DipEng, AAE MIMI,MSAE(Aust)

1246
-20%: 1000
2 Days



8778 1999
24 hr accident call

