

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0156/2021/TF
DATE : 18-Feb-21
WIP : 15931

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : M/S WHEALTHFIELDS LOHMANN (SG) PL
ADDRESS : 6 HARPER ROAD
#01-09
SINGAPORE 369674
TELEPHONE : HP +65 91888148
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070034930
VEHICLE NO : **SMS 6334 T**
MODEL CODE : AUDI Q8 3.0 TFSI QU
MODEL YEAR : 6/3/2020
ENGINE NO : DCB 067556
CHASSIS NO : WAUZZZF16KD016603
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Feb-21
PLACE OF ACCIDENT : DUA RESIDENCE CARPARK



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 6334 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00	250.
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY.	S/N \$ 280.00	x
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FERNDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,700.00	1000 1200.
SUB -TOTAL LABOUR CHARGES		: \$ 3,910.00	600 (per day)

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

(Bumper)
 Door
 Fender

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 6334 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES
5	TO RESPRAY FRONT BUMPER, RADIATOR GRILLE TRIM, RHS FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, BONNET, BOTH FRONT WHEEL ARCH TRIMS, RHS FRONT DOOR, RHS WING MIRROR COVER AND DOOR COVER.	\$ 6,550.00
6	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT. TO INSPECT RHS FRONT WHEEL SUSPENSION ASSY.	S/N \$ 520.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00
TOTAL LABOUR CHARGES		\$ 11,172.00

550 x 3 = 1650.
 Radiator Grille Trim : 200.
 Arch Trim : 200 x 2 = 400.
 Lower Spoiler : 200.

280



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 6334 T

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Dented</i>	1	\$	2,724.00	✓
2	FRONT BUMPER FIXING PARTS <i>Not in</i>	1	\$	378.00	+
3	FRONT BUMPER CLOSING ELEMENT - RH <i>Not in</i>	1	\$	120.00	+
4	FRONT HEADLIGHT WASHER NOZZLE BRACKET - RH <i>Not in</i>	1	\$	82.00	+
5	FRONT HEADLIGHT WASHER COVER - RH <i>Not in</i>	1	\$	82.00	+
6	FRONT RADIATOR GRILLE CLOSING ELEMENT - CENTER <i>Not in</i>	1	\$	278.00	+
7	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not in</i>	1	\$	210.00	+
8	FRONT BUMPER SPOILER - RH <i>Not in</i>	1	\$	211.00	+
9	FRONT RADIATOR TRIM <i>Not in</i>	1	\$	245.00	+
10	FRONT BUMPER AIR GRILLE - RH <i>Not in</i>	1	\$	183.00	+
11	FRONT BUMPER SUPPORT SENSOR - RH <i>Not in</i>	1	\$	29.00	+
12	FRONT BUMPER FORM FILLER PIECE <i>Not in</i>	1	\$	171.00	+
13	FRONT BUMPER CARRIER <i>Not in</i>	1	\$	964.00	+
14	FRONT BUMPER GUIDE SECTION - RH <i>Not in</i>	1	\$	44.00	✓
15	FRONT BUMPER BRACKET - LH / RH <i>?</i>	2	\$	68.00	?
16	FRONT BUMPER SENSOR <i>Not in</i>	1		TBC	+
17	FRONT BUMPER SEAL RING <i>Not in</i>	4	\$	14.00	+
18	HORN - HIGH TONE <i>Not in</i>	1	\$	195.00	+
19	HORN BRACKET <i>Not in</i>	1	\$	29.00	+
20	FRONT FENDER - RH <i>Dented</i>	1	\$	2,310.00	✓
SUB-TOTAL SPARE PARTS		:	\$	8,337.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 6334 T

S/N	PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS - RH <i>new</i>	1	\$	66.00	✓
22	FRONT FENDER BRACE - RH <i>Distorted</i>	1	\$	152.00	✓
23	FRONT FENDER BRACKET - RH <i>Distorted</i>	1	\$	65.00	✓
24	FRONT WHEEL HOUSING LINER RH - FRONT / REAR <i>torn</i>	1	\$	498.00	✓
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$	73.00	+
26	FRONT WHEEL SPOILER - RH <i>Not a</i>	1	\$	68.00	+
27	FRONT HEADLIGHT MOUNTING - RH <i>cracked</i>	1	\$	118.00	✓
28	FRONT HEADLIGHT - RH <i>lit</i>	1	\$	12,792.00	✓ photo
29	FRONT HEADLIGHT LIFT CYLINDER - RH <i>new</i>	1	\$	198.00	+
30	FRONT WHEEL ARCH TRIM - LH / RH <i>new</i>	1	\$	1,150.00	✓
31	WING MIRROR MOUNTING - RH <i>new</i>	1	\$	1,932.00	+
32	WING MIRROR COVER - RH <i>new</i>	1	\$	208.00	+
33	FRONT DOOR LOWER COVER - RH <i>new</i>	1	\$	507.00	+
34	FRONT TYRE RIM - RH <i>Repis</i>	1	\$	3,552.00	+
35	FRONT TYRE - RH <i>lit</i>	2		TBC	✓
36	SUNDRIES ?	1	\$	300.00	?
TOTAL SPARE PARTS		:	\$	30,016.00	
TOTAL LABOUR CHARGES		:	\$	11,172.00	
GRAND TOTAL		:	\$	41,188.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian L
SURVEYED DATE : 19/02/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 06 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT