

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Denise.

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0156/2021/TF 26-Mar-21 GLORY 1 of 1 SMS 6334 T AUDI Q8 3.0 TFSI QU
Quantity	Description	Unit Price	Amount
Labours			
1	FRONT BUMMPER CLOSING ELEMENT LHS <i>incl'd</i>	\$ 120.00	<i>—</i>
2	FRONT BUMPER GUIDE SECTION LHS <i>incl'd</i>	\$ 44.00	<i>—</i>
GRAND TOTAL		\$ 164.00	

For Premium Automobiles Pte Ltd

 Authorised Signature

Car in

24/3/21

w/p: 15931

Kiam

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Adrian

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 6334 T

S/N	PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES S/NETT	REMARKS
1	FRONT BUMPER <i>Dented</i>	1	\$	2,724.00	✓
2	FRONT BUMPER FIXING PARTS <i>Not in</i>	1	\$	378.00	+
3	FRONT BUMPER CLOSING ELEMENT - RH <i>*can be used</i>	1	\$	120.00	+
4	FRONT HEADLIGHT WASHER NOZZLE <i>Not in</i>	1	\$	82.00	+
4	BRACKET - RH	1	\$	82.00	+
5	FRONT HEADLIGHT WASHER COVER - RH <i>Not in</i>	1	\$	82.00	+
6	FRONT RADIATOR GRILLE CLOSING ELEMENT - CENTER <i>Not in</i>	1	\$	278.00	+
7	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not in</i>	1	\$	210.00	+
8	FRONT BUMPER SPOILER - RH <i>Repair</i>	1	\$	211.00	+
9	FRONT RADIATOR TRIM <i>Not in</i>	1	\$	245.00	+
10	FRONT BUMPER AIR GRILLE - RH <i>Not in</i>	1	\$	183.00	+
11	FRONT BUMPER SUPPORT SENSOR - RH <i>Not in</i>	1	\$	29.00	+
12	FRONT BUMPER FORM FILLER PIECE <i>Not in</i>	1	\$	171.00	+
13	FRONT BUMPER CARRIER <i>Not in</i>	1	\$	964.00	+
14	FRONT BUMPER GUIDE SECTION - RH <i>Dented</i>	1	\$	44.00	✓
15	FRONT BUMPER BRACKET - LH / RH ?	2	\$	68.00	?
16	FRONT BUMPER SENSOR <i>Not in</i>	1		TBC	+
17	FRONT BUMPER SEAL RING <i>Not in</i>	4	\$	14.00	+
18	HORN - HIGH TONE	1	\$	195.00	+
19	HORN BRACKET <i>Not in</i>	1	\$	29.00	+
20	FRONT FENDER - RH <i>Dented</i>	1	\$	2,310.00	✓
SUB-TOTAL SPARE PARTS			:	\$ 8,337.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 6334 T

S/N	PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES	REMARKS
				S/NETT	
21	FRONT FENDER ATTACHMENT PARTS - RH ^{new}	1	\$	66.00	✓
22	FRONT FENDER BRACE - RH ^{7istled}	1	\$	152.00	✓
23	FRONT FENDER BRACKET - RH ^{Distort + d}	1	\$	65.00	✓
24	FRONT WHEEL HOUSING LINER RH - FRONT / REAR ^{torn}	1	\$	498.00	✓
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ^{new}	1	\$	73.00	+
26	FRONT WHEEL SPOILER - RH ^{Not in}	1	\$	68.00	+
27	FRONT HEADLIGHT MOUNTING - RH ^{crushed}	1	\$	118.00	✓
28	FRONT HEADLIGHT - RH ^{let covered}	1	\$	12,792.00	✓ photo
29	FRONT HEADLIGHT LIFT CYLINDER - RH ^{new}	1	\$	198.00	+
30	FRONT WHEEL ARCH TRIM - LH / RH ^{new}	1	\$	1,150.00	✓
31	WING MIRROR MOUNTING - RH ^{new}	1	\$	1,932.00	+
32	WING MIRROR COVER - RH ^{new}	1	\$	208.00	+
33	FRONT DOOR LOWER COVER - RH ^{new}	1	\$	507.00	+
34	FRONT TYRE RIM - RH ^{Repair}	1	\$	3,552.00	+
35	FRONT TYRE - RH ^{let}	2		TBC	✓
36	SUNDRIES	1	\$	300.00	?
TOTAL SPARE PARTS			:	\$ 30,016.00	
TOTAL LABOUR CHARGES			:	\$ 11,172.00	
GRAND TOTAL			:	\$ 41,188.00	

Pirelli
 P Zero
 285/45 ZR21
 (113Y)

ALL CHARGES ARE INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Reviewed 26/03/21
 Admin L
 S/S