

REF: CC3/PIG 2100 246 / A/F3

Asst. Field By

ASSIGNMENT

From _____ Date _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: **2070034930**
 Claims No: **4789228831SG**
 Sum Insured: _____ Excess: **1400**
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: **06** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SMS6334T** Yr Regn: **2020 March**
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Audi Q8** C.C. **2995**
 Colour: **Silver** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **9325** T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: **WAUZZZF16KDC16603**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modl: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: **285/45R21**
 R: **285/45R21**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. **06** mm R/Bal. **06** mm
 L/Bal. **06** mm L/Bal. **06** mm
 D.O.A. _____ D.O.I. **19/02/21**
 Survey held at **Premium**
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OO AIG.
	Confirm repair cost of \$20,966.80 @ 6 days
	MV: 320K.
	PV: 106.8K.
	Nett: 213.2K.
	red: 20221.2; 98%

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: **6**
 Resurvey No. of Trip: _____

Report Format: _____
 Lump Sum / L.P. #: **20966.8**

Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech. Invs (\$))
 : Weekend (\$))

Survey Fee: _____
 Transportation: _____
) 3 + RS. SI
) Photos
) Others

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0156/2021/TF
DATE	:	18-Feb-21
WIP	:	15931

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	M/S WHEALTHFIELDS LOHMANN (SG) PL
ADDRESS	:	6 HARPER ROAD
	:	#01-09
	:	SINGAPORE 369674
TELEPHONE	:	HP +65 91888148
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070034930
VEHICLE NO	:	SMS 6334 T
MODEL CODE	:	AUDI Q8 3.0 TFSI QU
MODEL YEAR	:	6/3/2020
ENGINE NO	:	DCB 067556
CHASSIS NO	:	WAUZZZF16KD016603
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	17-Feb-21
PLACE OF ACCIDENT	:	DUA RESIDENCE CARPARK

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 6334 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00 250.	✓
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY.	S/N \$ 280.00	X X
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FERNDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,700.00 1000 1200	✓
SUB -TOTAL LABOUR CHARGES		\$ 3,910.00	600 (per day)

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 6334 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES
5	TO RESPRAY FRONT BUMPER, RADIATOR GRILLE TRIM, RHS FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, BONNET, BOTH FRONT WHEEL ARCH TRIMS, RHS FRONT DOOR, RHS WING MIRROR COVER AND DOOR COVER.	\$ 6,550.00 ✓ 2450.
6	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT. TO INSPECT RHS FRONT WHEEL SUSPENSION ASSY.	S/N \$ 520.00 ✓ 280.
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u><u>\$ 11,172.00</u></u>

(Bumper
Door
Fender)

550 x 3 = 1650.

Radiator Grille
Trim : 200.

Arch Trim : 200 x 2
= 400.

Lower Spoiler : 200.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 6334 T

S/N	PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES S/NETT	REMARKS
1	FRONT BUMPER <i>Rehd</i>	1	\$	2,724.00 ✓	2179.20
2	FRONT BUMPER FIXING PARTS <i>Not in</i>	1	\$	378.00 +	
3	FRONT BUMPER CLOSING ELEMENT - RH <i>new</i>	1	\$	✓ 120.00 +	95.60
4	FRONT HEADLIGHT WASHER NOZZLE BRACKET - RH <i>new</i>	1	\$	82.00 +	
5	FRONT HEADLIGHT WASHER COVER - RH <i>new</i>	1	\$	82.00 +	
6	FRONT RADIATOR GRILLE CLOSING ELEMENT - CENTER <i>new</i>	1	\$	278.00 +	
7	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$	210.00 +	
8	FRONT BUMPER SPOILER - RH <i>Regr</i>	1	\$	211.00 +	
9	FRONT RADIATOR TRIM <i>new</i>	1	\$	245.00 +	
10	FRONT BUMPER AIR GRILLE - RH <i>new</i>	1	\$	183.00 +	
11	FRONT BUMPER SUPPORT SENSOR - RH <i>Not in</i>	1	\$	29.00 +	
12	FRONT BUMPER FORM FILLER PIECE <i>new</i>	1	\$	171.00 +	
13	FRONT BUMPER CARRIER <i>new</i>	1	\$	964.00 +	
14	FRONT BUMPER GUIDE SECTION - RH <i>Rehd</i>	1	\$	44.00 ✓	35.12
15	FRONT BUMPER BRACKET - LH / RH <i>Not in</i>	2	\$	68.00 ? X	
16	FRONT BUMPER SENSOR <i>new</i>	1		TBC +	
17	FRONT BUMPER SEAL RING <i>new</i>	4	\$	14.00 +	
18	HORN - HIGH TONE <i>new</i>	1	\$	195.00 +	
19	HORN BRACKET <i>new</i>	1	\$	29.00 +	
20	FRONT FENDER - RH <i>Dented</i>	1	\$ ✓	2,310.00 ✓	1748
SUB-TOTAL SPARE PARTS		:	\$	8,337.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 6334 T

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS - RH <i>new</i>	1	\$ 66.00	✓
22	FRONT FENDER BRACE - RH <i>Distorted</i>	1	\$ 152.00	✓ 121.60
23	FRONT FENDER BRACKET - RH <i>Distorted</i>	1	\$ 65.00	✓ 51.28
24	FRONT WHEEL HOUSING LINER RH - FRONT / REAR <i>torn</i>	1	\$ 498.00	✓ 397.60
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 73.00	+
26	FRONT WHEEL SPOILER - RH <i>new</i>	1	\$ 68.00	+
27	FRONT HEADLIGHT MOUNTING - RH <i>cracked</i>	1	\$ 118.00	✓ 94.40
28	FRONT HEADLIGHT - RH <i>lit</i>	1	\$ 12,792.00	✓ photo 10 2337.6
29	FRONT HEADLIGHT LIFT CYLINDER - RH <i>new</i>	1	\$ 198.00	+
30	FRONT WHEEL ARCH TRIM - LH / RH <i>new</i>	1	\$ 1,150.00	✓ 9201
31	WING MIRROR MOUNTING - RH <i>new</i>	1	\$ 1,932.00	+
32	WING MIRROR COVER - RH <i>new</i>	1	\$ 208.00	+
33	FRONT DOOR LOWER COVER - RH <i>new</i>	1	\$ 507.00	+
34	FRONT TYRE RIM - RH <i>Repis</i>	1	\$ 3,552.00	✓
35	FRONT TYRE - RH <i>lit</i>	2	TBC	✓ 13072
36	SUNDRIES <i>Nec.</i>	1	\$ 300.00	? 7.68
TOTAL SPARE PARTS			\$ 30,016.00	
TOTAL LABOUR CHARGES			\$ 11,172.00	
GRAND TOTAL			\$ 41,188.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian
19/02/21

Not Authorised, 06 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

MIUM AUTOMOBILES

1. SINGAPORE 408699
323 FAX : 6841 1183
RA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0156/2021/TF
DATE	:	18-Feb-21
WIP	:	15931

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Hi Adrian,
6 days - ok - Jy - 15 Apr 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	M/S WHEALTHFIELDS LOHMANN (SG) PL
ADDRESS	:	6 HARPER ROAD #01-09 SINGAPORE 369674
TELEPHONE	:	HP +65 91888148
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070034930
VEHICLE NO	:	SMS 6334 T
MODEL CODE	:	AUDI Q8 3.0 TFSI QU
MODEL YEAR	:	06/03/2020
ENGINE NO	:	DCB 067556
CHASSIS NO	:	WAUZZZF16KD016603
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	17-Feb-21
PLACE OF ACCIDENT	:	DUA RESIDENCE CARPARK

PREMIUM AUTOMOBILES



100, SINGAPORE 408699
 2323 FAX : 6841 1183
 NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 6334 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
			\$ 1,930.00
5	TO RESPRAY FRONT BUMPER, RADIATOR GRILLE TRIM, RHS FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, BONNET, BOTH FRONT WHEEL ARCH TRIMS, RHS FRONT DOOR, RHS WING MIRROR COVER AND DOOR COVER.	\$ 6,550.00	\$ 2,450.00
6	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT. TO INSPECT RHS FRONT WHEEL SUSPENSION ASSY.	S/N \$ 520.00	\$ 280.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
	TOTAL LABOUR CHARGES	: \$ 11,172.00	\$ 4,852.00

SUMI
 06
 06
 9/0
 C I F
 ire



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 6334 T

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT FENDER ATTACHMENT PARTS - RH	1	\$		\$ 4,157.92
22	FRONT FENDER BRACE - RH	1	\$	66.00	
23	FRONT FENDER BRACKET - RH	1	\$	152.00	\$ 121.60
24	FRONT WHEEL HOUSING LINER RH - FRONT / REAR	1	\$	65.00	\$ 51.28
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	498.00	\$ 397.60
26	FRONT WHEEL SPOILER - RH	1	\$	73.00	
27	FRONT HEADLIGHT MOUNTING - RH	1	\$	68.00	
28	FRONT HEADLIGHT - RH	1	\$	118.00	\$ 94.40
29	FRONT HEADLIGHT LIFT CYLINDER - RH	1	\$	12,792.00	\$ 10,233.60
30	FRONT WHEEL ARCH TRIM - LH / RH	1	\$	198.00	
31	WING MIRROR MOUNTING - RH	1	\$	1,150.00	\$ 920.00
32	WING MIRROR COVER - RH	1	\$	1,932.00	
33	FRONT DOOR LOWER COVER - RH	1	\$	208.00	
34	FRONT TYRE RIM - RH	1	\$	507.00	
35	FRONT TYRE - RH	1	\$	3,552.00	
		2		TBC	
	SUPPLEMENTARY				\$ 130.72
36	SUNDRIES	1	\$	300.00	\$ 7.68
TOTAL SPARE PARTS		:	\$	30,016.00	\$ 16,114.80
TOTAL LABOUR CHARGES		:	\$	11,172.00	\$ 4,852.00
GRAND TOTAL		:	\$	41,188.00	\$ 20,966.80

NA
INA

SUMI

06
06
102

RO

file

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

AUTOMOBILES

Phone: 6841 408699
 Fax: 6841 1183
 Email: khal@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
 Attn: Mr. Adrian Ling - Motor Claims Dept
 Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
 Date
 Service Advisor
 Pages
 Regn No
 Model No

PA/OD/0156/2021/TF
 26-Mar-21
 GLORY
 1 of 1
 SMS 6334 T
 AUDI Q8 3.0 TFSI QU

Quantity	Description	Unit Price	Amount
Labours			
1	FRONT BUMPPER CLOSING ELEMENT LHS	\$ 120.00	\$ 95.60
2	FRONT BUMPER GUIDE SECTION LHS	\$ 44.00	\$ 35.12
GRAND TOTAL		\$ 164.00	\$ 130.72

3 paid

For Premium Automobiles Pte Ltd

 Authorised Signature