

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHB2394 U
 MAKE HYUNDAI
 MODEL I-40

DATE 24/01/21
 MVA CHIANG/ NTUC

L/S

Qty	Parts Description/ Labour	Type	Unit Price	Amount
				\$2,256.40
1	FRONT LH DOOR PANEL			\$172.70
1	FRT DOOR POWER MOTOR LH			\$490.80
1	FRT DOOR INNER LOCK LH			\$132.30
1	FRT DOOR HANDLE			\$3,052.20
	SUB TOTAL			\$610.44
	20.00%			\$2,441.76
	DISCOUNTED TOTAL			
				\$75.00
1	FRONT DOOR COMFORT STICKER			\$100.00
1	FRONT DOOR ADVERTISEMENT			\$167.50
	Labour Charge			\$500.00
	Panel Beating			\$300.00
	Spray Painting Charge			\$60.00
	Remove/refix door parts			\$60.00
	Tuff coat			\$920.00
	TOTAL LABOUR			
	ESTIMATE TOTAL			\$3,529.26
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

CUT
?
?
DEF

NEL
NEL

280
250
30
40

NA2 LKIC
 17/12/2021 1635
 L/S
 2 DAYS
 CHECK ITEM PHOTOS
 AFTER REPAIR PHOTOS

LKIC Auto Consultants hence notify the Repairer of the following:

- To resurvey help with spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: