

COMFORT DEL GRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date 17.02.2021

Time 16.04.18

Page 1/2

COMPANY THIRD PARTY'S CLAIMS (CAS)
CUSTOMER 7010045
ADDRESS COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

NTUC - CIP
L/S
LKK - Naz

JOB NO 305454252
REGN NO SHC3036S
MILEAGE 000000000
MAKE HYUNDAI
MODEL IONIQ(G2)
DATE OF REGN 15.08.2018
DATE/TIME IN 17.02.2021 13.30
ACCIDENT DATE 16.02.2021

JOB PARTS DESCRIPTION

QTY IND UNIT PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	X R / CRK	
0002 04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00	/ DEF	DEF
0003 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	X SVC	SVC
0004 09-01-9999-0068-A	REVERSE SENSOR	1	180.00	10.00	162.00	X SVC	SVC
0005 FNPS	REAR NO PLATE W/TRIM COVER	1 N	55.00	10.00	49.50	/ CRK	
0006 04-01-0104-2288-G	REAR BUMPER BEAM	1	394.80	20.00	315.84	? X SVC	

SUB-TOTAL : 1,273.46

JOB NATURE

0000 PB	PANEL BEATING	400.00	250	350
0001 SP	SPRAYPAINT CHARGE	200.00	250	
0002 L	R/T REVERSE SENSOR	120.00	30	

SUB-TOTAL : 820.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 17.02.2021

Time: 16:04:18

Page: 2

REPAIR ESTIMATE NTUC - CPT L/S

LKK - NAZ

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305454252
REGN NO : SHC3036S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 15.08.2018
DATE/TIME IN : 17.02.2021 13:30
ACCIDENT DATE : 16.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

Lmkf

TOTAL : 2,093.46

MVA NAME & SIGNATURE
DATE:

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE:

NAZ LKK

17/2/2021 1615

L/S

2 Days

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: