

SMH7170A-

TP AXA.

Honda Jazz

Jasper.

JHMGK3850KS205656

Front Number Plate	Dented	30(SN)	✓
Front Number Plate Holder	dented	30(SN)	✓
Front Number Plate Garish.	dented	6620	✓
Front Bumper	Dented	598.40	✓
Front Bumper Clips.	m	30(SN)	✓
Front Bumper Side Holder x 02	m	25.4 x 2 = 50.80	✓
Front Bumper Tow Cover	Not m	18.40	+
Front Bumper Lower Grille	Dented	102.40.	✓
Front Bumper Fog Lamp Cover	crushed	78 x 2 = 156.	✓
Front Bumper Reinforcement.	Dented	203.30.	✓
Front Bumper Side Black Strip x 02	crushed	29 x 2 = 58	✓
Front Grille	crushed	364.57	✓
Front Grille Chrome Moulding.			
Front Grille Logo	m	39.40	✓
Front Grille Clips.	m	20(SN)	✓

SMH7170A.

585.90

Headlamp x 02	PH cancelled	585.90 x 2 = 1171.80
Headlamp lower Bracket x 02	new	35 x 2 = 70
Front Support Panel. Pair		474.30 x
Front Support Panel Air Duct.	re-ltd	58.90 -
Front Support Panel Air Duct clips	new	10 (SN) -
Air Con Condenser,	new	704.40 x
Air Con Condenser Air Guide x 02	re-ltd	39.4 x 2 = 78.80
Air Con Condenser Air Guide Clips	new	20 (SN) -
Bonnet	Repair	685.40 x
Bonnet lock.	new	49.80 x
Front Fender x 02	Repair	481.4 x 2 = 962.80 x

SMH 7170A.

Rees Number Plate	} 14 New	30(SN) ✓
Rees Number Plate Holder		30(SN) ✓
Rees Bumper	Distorted	592.70 ✓
Rees Bumper Clips	m	30(SN) ✓
Rees Bumper Side Holder x 02	m	$28.2 \times 2 = 56.40$ ✓
Rees Bumper Lower Centre Garnish	could	85.90. ✓
Rees Bumper Lower Side Garnish x 02.	could	$45.9 \times 2 = 91.80$ ✓
Rees Bumper Under Cover LH	could	75.90 ✓
Rees Bumper Under Cover clips.	m	20(SN) ✓
Rees End Panel	Distorted	355.40 ✓
Rees End Panel Top Garnish	could	198.10. ✓
Rees End Panel Top Garnish Clips	per	20(SN) ✓
Taillamp x 02	at	$372.8 \times 2 = 745.60$ ✓
Taillamp Panel x 02 Repair		$176.2 \times 2 = 352.40$ ✓
Tailgate	Distorted	882.90 ✓
Tailgate Lock	Distorted	197.40. ✓
Tailgate Weatherstripe	at	145.60. ✓

SMH 7170A.

Tailgate Inner Trim Board	could	241.20 ✓
Tailgate Inner Trim Board Clips	m	30(SN) ✓
Tailgate Reflector x 02	cut	$238.5 \times 2 = 477$ ✓
Tailgate Outer Garnish	M m	286.80 +
Tailgate G/S Moulding	Nec	104.90 ✓
Tailgate G/L Sealant		60(SN) ✓
Harder Logo.		32.40 ✓
Jazz Wordery.		38.50 ✓
Rear Camera.	NH m	480(SN) +
Rear Fender Inner Trim Board x 02	could	$285.4 \times 2 = 570.80$ ✓
Rear Fender Inner Trim Board Clips	m	60(SN) ✓
Rear Fender Inner Shield x 02	M m	$122.9 \times 2 = 245.80$ +
Rear Fender Inner Shield clips		50(SN) X
Spare Tyre Panel	Distorted	865.70 ✓
Spare Tyre Panel Insulation Pad	m	300(SN) ✓
Spare Tyre Panel Top Cover	Rehd	287.50 ✓

SMH7170A.

Tools Sponge Tray. Behind 289.40. ✓

Rear Exhaust Pipe. Bent 652 ✓

Rear Exhaust Mounting. ^{NP} m 35.40. ✗

Rear Exhaust Gasket. New 25(su). ✓

Rear Exhaust Heat Shield. ^{Torn} 78.40. ✓

Centre Exhaust Pipe. ^{NP} m 876.40. ✗

Reverse Sensor 2nd ~~280(su)~~ 2nd(su)

Panel Beating (Front) ~~1400~~ 500

Spray Painting (Front) ~~1400~~ 500

Wiring (Front) ~~50~~ 30

To spray tuff coat (Front) ~~120~~ 30

To remove condenser and to top up air con gas. ~~100~~ 60

To remove radiator and to top up coolant. ~~100~~ 60

Panel Beating (Rear) ~~1500~~ 1300

Spray Painting (Rear) ~~1400~~ 1000

Wiring (Rear) ~~50~~ 30

To spray tuff coat (Rear). ~~150~~ 80

SMH7170A.

To remove reverse sensor

~~100~~ 50

To remove rear camera.

~~100~~ 50

To remove video recorder

~~100~~ 50

To remove upholstery and rear seat.

~~320~~ 200

To remove tailgate glass

~~180~~ 120

To transfer tailgate fittings.

~~150~~ 80

To remove rear and centre exhaust pipes.

~~300~~ 80

List: 9378.50

Len 20/ : 7502.80

S.N: 785

Labour: 4220

total: 12507.80

L/S: 10K.

12 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10,000