



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367N  
GST Reg No. MR-850G111-X

# ESTIMATE FOR SMS8556G

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT  
64 CECIL STREET  
#04/#05 IOB BUILDING  
SINGAPORE 049711  
63476100

## Vehicle & Document Information

WIP No 48393  
Reg No/Reg Date SMS8556G / 19/03/2020  
Date In/Mileage 1 / 0  
Chassis No WDD2130802A7493895  
Engine No 26492080024177  
Make/Model MB/E 200 SEDAN  
Colour/Trim 028 890 Cavansite B/ 042 201 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
W1000576	Credit	15/02/2021/ 16:56	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
A BPILAB				969 1920.00
DISASSEMBLE AND REPAIR FRONT BUMPER & REFINISH.				600 1200.00
A BPIRES				
RESPRAY FRONT BUMPER				
M BPNSUN				
POLICY NO/ACC DATE : 2070051874-01 // 11/02/2021				
DRIVE IN/TP VEHICLE NO. : 15/02/2021 // SMA6716U -				
DATE IN/DATE SURVEY:				
BY/AUTHORIZED ON :				
A BPILAB			0.10	380.00 /
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				120.00 ✓
A BPILAB				
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT				
M LH/ FRONT BUMPER MOUNTING-PAIR	1.00	9.14	00.00	9.14
M LH/ BASIC MOUNTING FOR BUMPER	1.00	68.36	00.00	68.36
M LH/ HEADLAMP UNIT	1.00	3520.82	00.00	3520.82
M FRONT BUMPER	1.00	1316.78	00.00	1316.78

Kerlyn Ong Kai Li  
DID : 6771 4420 HP : 9186 5113  
Email : kerlyn.ong@cyclecarriage.com.sg  
Cycle & Carriage Industries Pte Ltd  
Customer Service Centre - Pandan Loop

Steve CLKK) Mr P/L  
15/3/21, 11.00am  
P/P, My Bel SM

Confirmed & accepted by

3 days

7% GST on 8535.10  
Nett 8,535.10  
597.46

Total Payable 9,132.56

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated Costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

\* Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg