



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 1111L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	CRUMPLED	1,700.00	1,332.00
2	FRONT BUMPER BRACKET @\$170.00	O/S BROKEN	340.00	135.00
2	FRONT BUMPER RETAINER @\$188.00	O/S BROKEN	376.00	95.00
1	FRONT BUMPER REINFORCEMENT	BENT	900.00	630.00
2	FRONT BUMPER REINFORCEMENT BRACKET @\$300.00	SERVICEABLE	600.00	-
1	FRONT FOG LAMP COVER RH	CRUMPLED	390.00	160.00
1	FRONT FOG LAMP RH	CRACKED	450.00	220.00
1	FRONT NOZZLE COVER RH	CRUMPLED	160.00	138.50
1	FRONT NOZZLE MOTOR	CRUMPLED	330.00	168.82
1	FRONT HEADLAMP RH	CRACKED	3,950.00	2,445.00
1	AIR DUCT FRONT BOTTOM	SERVICEABLE	190.00	-
2	PDC SENSOR @\$720.00	SERVICEABLE	1,440.00	-
2	PDC SENSOR HOLDER @\$150.00	SERVICEABLE	300.00	-
1	SENSOR WIRE HARNESS	SERVICEABLE	295.00	-
1	AIR DUCT FRONT BOTTOM	SERVICEABLE	195.00	-
1	FRONT LH FENDER	DENTED	806.15	806.15
	LESS 10% DISCOUNT		-1,242.22	-613.05
			11,179.93	5,517.42
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	40.00	40.00
			40.00	40.00
<b><u>LABOUR</u></b>				
	CHECK FRONT WIRING AND LIGHTNING SYSTEM.		80.00	30.00
	REMOVE AND RENEW FRONT SENSOR.	NOT NECESSARY	120.00	-
	DIAGNOIS CHECK AND CLEAR CODE.		400.00	50.00
	PANEL BEATING ON AFFECTED AREAS AND RENEW PARTS.		800.00	500.00
	SPRAY PAINTING ON AFFECTED AREAS.		900.00	800.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	40.00
			2,420.00	1,420.00
	<b>GRAND TOTAL</b>		<b>13,639.93</b>	<b>6,977.42</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,600.00</b>

Report Ref No. CS/SMO21002452/QUqf3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.