



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO21002452/QUqf3q2 Date: 17/03/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 5017A	Veh. Inspected	SLJ 1111L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2100562/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	22/02/2021
2. Vehicle Particulars & Condition			
Make & Model	BMW 328I	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WBA3A52050F254463	Colour	GREY
Odometer	123489 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	PIRELLI	6 mm
L/H Front Tyre	225/40 R18	PIRELLI	6 mm
R/H Rear Tyre	225/40 R18	PIRELLI	6 mm
L/H Rear Tyre	225/40 R18	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/02/2021	Inspection Date	22/02/2021
Survey held at	AUTO BULLOX PTE LTD 53 UBI AVENUE 1 #01-19 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	