

AUTO BULLOX PTE LTD

53 Ubi Avenue 1#01-25 Paya Ubi Industrial Park Singapore 408934

Tel: 6844 4290 Fax: 6841 6043 Kaman Koh: 9769 9299 Email: motoricarzgarage@gmail.com

UEN:201919765N

Estimation

Vehicle No: SJL1111L

Make/Model: BMW 328i

Date of Accident: 19/02/2021

Surveyor Name: Mr. Kenneth Kong (LKK)

No.	Description	Unit	Unit Price	Amount (S\$)
Parts Replacement:				
1	FRONT BUMPER / CRU	1	1,700.00	1,700.00
2	FRONT BUMPER BRACKET RH / BR	1	170.00	340.00
3	FRONT BUMPER RETAINER RH / BR	1	188.00	376.00
4	FRONT BUMPER REINFORCEMENT / BT	1	900.00	900.00
5	FRONT BUMPER REINFORCEMENT BRACKET X SVC	2	300.00	600.00
6	FRONT FOG LAMP COVER RH / CRU	1	390.00	390.00
7	FRONT FOG LAMP RH / CRA	1	450.00	450.00
8	FRONT NOZZLE COVER RH / CRU	1	160.00	160.00
9	FRONT NOZZLE MOTOR / CRU	1	330.00	330.00
10	FRONT HEADLAMP RH / CRA	1	3,950.00	3,950.00
11	AIR DUCT FRONT BOTTOM X SVC	1	190.00	190.00
12	PDC SENSOR X SVC	2	720.00	1,440.00
13	PDC SENSOR HOLDER X SVC	2	150.00	300.00
14	SENSOR WIRE HARNESS X SVC	1	295.00	295.00
15	AIR DUCT FRONT BOTTOM X SVC	1	195.00	195.00
16	FRONT LH FENDER / DD	1	806.15	806.15
				12,422.15
			Less 10%	1,242.22
				11,179.94
S/Nett items:				
17	FRONT BUMPER CLIP / Nec	1set	40.00	40.00
				40.00
Labour to:				
18	CHECK FRONT WIRING AND LIGHTNING SYSTEM		80.00	80.00
19	REMOVE AND RENEW FRONT SENSOR		120.00	120.00
20	DIAGNOIS CHECK AND CLEAR CODE		400.00	400.00
21	PANEL BEATING ON AFFECTED AREAS AND RENEW PARTS		800.00	800.00
22	SPRAY PAINTING ON AFFECTED AREAS		900.00	900.00
23	APPLY ANTI RUST ON AFFECTED AREAS		120.00	120.00
				2,420.00
Total Parts Replacement Amount				11,219.94
Total Amount for Labour				2,420.00
Total Amount				13,639.94

Repair day 4 days

L/S
Sun Pin (LKK)
01/03/2021

L/S
\$ 5,600
4 days

5,517.42
40
1,420
6,977.42
- 20%
5,581.94