

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002463/KGA3Q2
Date: 08/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070170010
Claimant Vehicle No :	SJQ902P	Insured Vehicle No :	SMX8855S
Date of Loss:	14/02/2021	Nature of Claim:	TP
		Claim No:	0428221699SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ902P		
Make & Model:	HONDA STREAM, 1.8 X (A)	Engine No:	R18A1801053
Reg. Date:	24/04/2009 (Man. Year: 2008)	Chassis No:	RN61091080
Colour:	Metallic Grey	Odometer:	284636 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	CST 9 mm	Rear Left Side:	CST 5 mm
Front Right Side:	CST 9 mm	Rear Right Side:	CST 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,972.66	2,307.94	664.72	22.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,400.00	1,180.00	45.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,552.66	3,707.94	1,844.72	33.22
Approved Total (Overridden) (S\$)		2,950.00		

Nett Amount (S\$)	5,552.66	2,950.00	2,602.66	46.87
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Car Rental (6.0 x S\$70.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,677.45		

INSPECTION

Date of Assignment: 22/02/2021

Date Inspected: 08/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Ngs Automotive (HQ)
 BLK 10 AMK IND PK 2A #02-01
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRUNK LID	Bent	966.40 FL	*966.40 FL
2	1		*GARNISH ,TRUNK LID	Warped	196.55 FL	*196.55 FL
3	1		*OUTER HANDLE ,TRUNK LID	Serviceable	91.00 FL	*- FL
4	1		*INNER LOCK ,TRUNK LID	Dented	128.20 FL	*128.20 FL
5	1		*RUBBER ,TRUNK LID (50%)	Dented / Distorted	126.40 FS	*79.00 FS
6	1		*REAR BOOT PULL COVER	Missing	28.70 FL	*28.70 FL
7	1		*REAR BUMPER	Buckled	689.20 FL	*689.20 FL
8	2		*RETAINER RH/LH ,RR BUMPER	Serviceable	53.80 FL	*- FL
9	1		*END PANEL	Serviceable	333.10 FL	*- FL
10	1		*EMBLEM STREAM	Necessary	34.30 FS	*34.30 FS
11	1		*BADGE	Necessary	52.40 FS	*52.40 FS
12	1		*NO PLATE W/CASING	Dented	50.00 FS	*45.00 FS
13	1		*REVERSE SENSOR	Dented	280.00 FS	*200.00 FS
14	1		*PARKING CAMERA	Cracked	380.00 FS	*250.00 FS
15	1		*SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,470.05	2,709.75
- List Item Discount on L Items 20.00/20.00% (\$)	497.39	401.81
Total Parts (\$)	2,972.66	2,307.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSFER DOOR MECHANISM	New	150.00	60.00
2	REMOVE REAR GLASS & TRANSFER TO NEW DOOR	New	180.00	120.00
3	REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT /ATTACHMENT ,STRAIGHTEN CHASSIS MEMBER ,REPAIR /RESHAPE DENTED PANEL ,REPLACE DAMAGED PARTS .REFIT INTO POSITION	New	1,200.00	600.00
4	SPRAY PAINTING ON RR BOOT LID ,RR BUMPER ,RR END PANEL & ETC	New	1,000.00	600.00
5	CHECK WIRING /LIGHT PROPER FUNCTION	New	50.00	20.00
Gross Labour Cost (\$\$)			2,580.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >