

PREMIER AUTOMOTIVE SERVICES PTE LTD


23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

22-Feb-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8938 L

1 pc	Boot lid	\$	1,119.00 / DO
1 pc	Boot lid lock	\$	99.00 / BT
1 pc	Bootlid lock cable	\$	35.00 X SVC
1 pc	Bootlid striker	\$	21.00 X SVC
1 pc	Bootlid emblem	\$	27.00 / NBL
1 pc	Bootlid CRDi	\$	29.00 / NBL
1 pc	Boot lid rubber weatherstrip	\$	96.00 / DEF
1 pc	Boot lid lower garnish	\$	290.00 / CRK
2 pcs	Bootlid hinges @ \$66.00	\$	132.00 X SVC
2 pcs	Rear license plate lamp @ \$30.00	\$	60.00 X SVL
2 pcs	Bootlid hinge torsion bar @ \$33.00	\$	66.00 X SVL
1 pc	Handle trunk lid hook	\$	5.00 X SVL
1 pc	Bootlid inner trim	\$	190.00 X SVC
1 pc	End panel	\$	250.00 / DEF
1 pc	End panel inner garnish	\$	74.00 X SVC
1 pc	Rear bumper	\$	696.00 / CRK
1 pc	Rear bumper lower cover	\$	206.00 / CRK
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00 X SVC
1 pc	Rear bumper inner sponge	\$	114.00 / CRK
1 pc	Rear bumper reinforcement	\$	607.00 / DO
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00 / BT
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00 X SVC
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00 X SVC
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00 X SVC
2 pcs	n/s & o/s tail lamp @\$421.00	\$	842.00 / CRK
2 pcs	n/s & o/s reflector @\$350.00	\$	700.00 X
1 pc	Spray tyre clamp	\$	6.00 / SMCK
1 pc	Exhaust pipe	\$	1,009.00 X SVL
1 pc	Exhaust pipe hanger	\$	40.00 X SVL
		\$	7,043.00
Less 10%		\$	704.30
		\$	6,338.70



LH SVL ✓
RH SVL X

22-Feb-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8938 L

S/NETT

1 set	Rear bumper clips	\$	48.00	NEL
1 set	End panel inner garnish clips	\$	30.00	40.00 XSVL
1 set	Bootlid inner trim clips	\$	52.00	XSVL
1 set	Bootlid lower garnish clips	\$	60.00	NEL
1 set	Bootlid stickers	\$	100.00	NEL
2 set	Rear n/s & o/s fender inner shield clips	\$	56.00	XSVL
1 set	Reverse sensor	\$	280.00	300.00 XSVL NW
1 pc	Rear bumper top protector	\$	80.00	XNN
1 pc	Rear no. plate with casing	\$	50.00	XSVL
1 pc	Sealant	\$	50.00	40.00 NEL
	Sundry	\$	50.00	40
	Towing Fee	\$	50.00	XNN
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	30
	To dismantle / replace new exhaust pipe	\$	120.00	XNN
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	60
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel, rear n/s & o/s fenders. Including knock-out, straighten, repair, reshape and adjust of the rear panel		\$1,000.00	800
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, bootfloor	\$	1,200.00	630
	To apply rustproofing on the repaired and replaced panels.	\$	120.00	50
		\$	9,984.70	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NA2 LKIC

23/2/2021 1345

LIS

6 DAYS

CHECK ITEM PHOTO (request net book value - vehicle left) gr dd
AFTER PAINT PHOTO