



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/022021/4729
Accident date: 18/2/2021
Your Ref : XE3054P

Tax Invoice:
Date : 20/2/2021

Motor Claim Department
MSIG INSURANCE (SINGAPORE) PTE LTD
No.4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SKM3984S
Model : VOLVO V40 T2 (A)

	Parts Prices
1 pc Rear RH door / DD	\$ 2,040.60 1962
1 pc Rear RH door rubber / NEC	\$ 127.50
1 pc Rear RH door outer moulding / NEC	\$ 118.40
1 pc Rear RH fender / CR4	\$ 1,355.70
1 pc Rear RH fender quarter glass moulding with glass / No\$	\$ 448.60 405
1 pc Rear RH taillamp X / CR4	\$ 407.00 372.05
1 pc Rear bumper / CR4	\$ 1,531.20
1 pc Rear bumper RH side retainer / BK	\$ 93.30
10 pcs Rear bumper clips @ \$6.10 / NEC	\$ 61.00
1 pc RH side skirt X / CR4	\$ 534.40
1 pc Rear RH wheel sport rim / SC6	\$ 648.50 580
1 pc Rear RH wheel shock absorber ? X SVC	\$ 227.70 X
1 pc Rear RH wheel knuckle arm ? / BT	\$ 695.30 644.31
1 pc Rear RH wheel knuckle arm bearing ? / Jam	\$ 462.60 396.27
1 pc Rear RH wheel top arm ? / BT	\$ 183.50
1 pc Rear RH wheel lower arm (big) ? / BT	\$ 511.70 435
1 pc Rear RH wheel lower arm (small) ? / BT	\$ 151.20
1 pc Rear RH wheel side control arm ? X SVC	\$ 711.30 X
1 pc Rear crossmember ? / BT	\$ 1,911.20 1,856
	\$ 12,220.70 10,811.83
Less 5%	\$ (611.04) - 5%
	\$ 11,609.67 10,271.24
1 pc Rear RH fender quarter glass gum / NEC	\$ 60.00 N 30
1 pc Rear RH wheel tyre X SVC	\$ 380.00 N X

Vin's

AUTOMOTIVE GROUP

Our Ref : TP/022021/4729
Accident date: 18/2/2021
Your Ref : XE3054P

Tax Invoice:

Date : 20/2/2021

A Sin Ming Autochy,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Towing (inv.)	X	\$ 150.00	✓
To check wheel alignment		\$ 150.00	60
To remove and refix rear undercarriage		\$ 380.00	200
To remove and refix petrol tank		\$ 120.00	60
To remove and refix seat cushion and roof lining		\$ 280.00	100
To repair rear damages		\$ 1,200.00	800 900
To spray painting		\$ 1,300.00	700 1,000
		<u>\$ 15,629.67</u>	2,500

VIN'S MOTOR PTE LTD



Repair dy - 67 days

~~PIP~~ PIP
before ~~PIP~~ paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sun Pin (LKK)
22/02/2021

TP without prejudice

Sunpin@lkkauto.com
8661 2621

PIP
\$ 12,771.24

7 days

10,271.24
2,500
12,771.24