

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Phoebe Xie

Date: 08 Mar 2021

## **Preliminary Advice**

Insured Vehicle No	: GBJ1403M	Accident Date	: 21/02/2021
TP Vehicle No	: SDX8832P	Assignment Date	: 22/02/2021
Make	: MERCEDES-BENZ E250	Est. Duration of Repair	: 4
Date of Inspection	: 01/03/2021		
Inspection At	: SPECIALISTS MOTOR PTE LTD (HQ) BLK 3018A UBI ROAD 1, #01-24/25/26 SINGAPORE 408711		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,505.40
Revised Amount	:S\$	5,872.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,872.00
Lump Sum Repair	:S\$	4,650.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Survey on WP