

RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
 Blk 8 , Kaki Bukit Avenue 4 , #02-24
 Premier @ Kaki Bukit Singapore 415875
 Email: claims@rico60.com
 Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
Total	
Lump Sum	
ERV	

TO: AIG
 Vehicle No : GBD 8055 U
 Make & Model : TOYOTA HIACE
 DATE:18/2/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE	
1	TAILGATE X Repair	1	\$ 2,172.70	\$ 2,172.70	
2	TAILGATE LOGO	1	\$ 89.00	\$ 89.00	51.1
3	TAILGATE STICKER 'TOYOTA HIACE' X	1	\$ 125.00	\$ 125.00	35.75
4	TAILGATE STICKER '1200KG'	1	\$ 125.00	\$ 125.00	30
5	TAILGATE INNER LOCK X	1	\$ 235.00	\$ 235.00	
6	TAILGATE WEATHERSTRIP X	1	\$ 408.40	\$ 408.40	
7	TAILGATE WEATHERSTRIP PROTECTOR X	1	\$ 217.00	\$ 217.00	
8	TAIL LAMP RH / CAA	1	\$ 489.00	\$ 489.00	374.45
9	TAILLAMP LOWER GARNISH RH / BR	1	\$ 125.00	\$ 125.00	104.7
10	TAILLAMP LOWER GARNISH RETAINER RH / BR	1	\$ 75.00	\$ 75.00	38
11	REAR FENDER RH X Repair	1	\$ 1,618.00	\$ 1,618.00	
12	REAR BUMPER / EL	1	\$ 598.00	\$ 598.00	374.4
13	REAR BUMPER SIDE RETAINER X NV	1	\$ 68.00	\$ 68.00	
14	REAR BUMPER BOTTOM BRACKET X NV	4	\$ 56.00	\$ 224.00	
15	REAR BUMPER STEP PANEL / BT	1	\$ 395.00	\$ 395.00	235
16	REAR END PANEL (OUTER) X Repair	1	\$ 565.00	\$ 565.00	
17	REAR END PANEL RH(EXTEND) / BUC	1	\$ 685.00	\$ 685.00	591.6
18	REAR EXHAUST PIPE X Repair	1	\$ 689.00	\$ 689.00	
19	REAR EXHAUST MOUNTING X	1	\$ 65.00	\$ 65.00	
20	REAR EXHAUST BRACKET X NV	1	\$ 121.00	\$ 121.00	
Subtotal :				\$ 9,089.10	1835
Less 25%				\$ 1,817.82	
Parts Total :				\$ 7,271.28	1376.25

SPECIAL NETT				QTY	UNIT PRICE	PRICE	
1	TAILGATE WINDSCREEN SEALANT X			1	\$ 80.00	\$ 80.00	
2	TAILGATE WINDSCREEN INNER SEAL X			1	\$ 60.00	\$ 60.00	
3	TAILGATE SEALANT X			1	\$ 80.00	\$ 80.00	
4	TAILGATE 70KM STICKER / MC			1	\$ 50.00	\$ 50.00	101.5
5	REAR BUMPER CLIP / MC			1	\$ 60.00	\$ 60.00	30.
6	TAIL LAMP CLIP /			1	\$ 30.00	\$ 30.00	20
7	REAR END PANEL (OUTER) SEALANT X			1	\$ 150.00	\$ 150.00	50.
8	REAR END SIDE PANEL SEALANT X			1	\$ 80.00	\$ 80.00	40.
9	REVERSE SENSOR X			1	\$ 380.00	\$ 380.00	
						\$ 970.00	105
LABOUR						PRICE	
PANEL BEATING, REMOVAL AND REPLACING PARTS						\$ 1,200.00	500
TO SPRAY PAINT AFFECTED AREA						\$ 1,200.00	600
WIRNING, BULB CHECKING						\$ 50.00	30
CONDUCT WATER LEAKAGE TEST						\$ 100.00	X
REMOVE AND REFIX TAILGATE WINDSCREEN						\$ 150.00	X
TRANSFER TAILGATE MECHAISM						\$ 150.00	X
REMOVE AND REFIX CARPET ,TRIM AND INTERIOR						\$ 400.00	X
REMOVE AND REFIX REAR EXHAUST						\$ 200.00	50
							1180
LABOUR TOTAL						\$ 3,450.00	
					Total Parts Cost	\$ 8,241.28	
					Total Labour Cost	\$ 3,450.00	
					Total Repair Cost	\$ 11,691.28	

APPROVED DETAILS

NO. OF WORKING DAYS

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

2661.25

-20%: 2100

After repair photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: