

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

*Not withold
L1 Sm &
Resurvey After Paint*

4 days

REPAIR ESTIMATE FOR GBD2764X

No.	Qty	Nett Items	Price	Notes
1	1	Rear RH side gate	\$ R 2,600.60	X
2	1	Rear RH side gate lower lock catch	\$ R 85.10	X
3	1	Rear RH side lower rubber stopper bracket	\$ R 183.40	✓
4	1 set	Rear RH side lower rubber stopper	\$ R 14.00	✓
5	1	Rear tailgate	\$ R 1,399.70	✓
6	1	Rear tailgate "NISSAN" emblem	\$ R 125.60	✓
7	1	RH taillamp bracket	\$ R 57.40	✓
8	1	RH taillamp	\$ CM 148.70	✓
9	1	Rear number plate bracket	\$ R 48.50	X
10	1	Rear deck end panel	\$ R 848.60	✓
			\$ 5,511.60	
Less 10%			\$ 551.16	
Total :			\$ 4,960.44	

Special Nett Items		Price	Notes
11	1 set	Rear RH side gate company sticker set	\$ R 350.00 X
12	1	Rear tailgate inner metal protection panel	\$ R 450.00 300in
13	1	Rear tailgate LH "70km/h" sticker	\$ R 15.00 125in
14	1	Rear tailgate RH "13pax" sticker	\$ R 15.00 125in
15	1	Rear number plate	\$ S 45.00 X
16	1 set	Reverse sensor	\$ S 280.00 X
Total :		\$ 1,155.00	

Labour		Price	Notes
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,000.00	700
2	To putty and spray Spray Paintings charges.	\$ 1,000.00	600
3	To check wirings & lightings.	\$ 40.00	200
4	To replace & re-install reverse sensors.	\$ 80.00	500
5	To supply and apply anti rust treatment	\$ 80.00	600
Total :		\$ 2,200.00	

Total Parts and Labour : \$ 8,315.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____