

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Withheld
L1 Sm @ 3,250.00
Resurvey After Paint

4 days

REPAIR ESTIMATE FOR GBD2764X

No.	Qty	Nett Items	Price	Notes
1	1	Rear RH side gate	\$ 2,600.60	X
2	1	Rear RH side gate lower lock catch	\$ 85.10	X
3	1	Rear RH side lower rubber stopper bracket	\$ 183.40	✓
4	1 set	Rear RH side lower rubber stopper	\$ 14.00	✓
5	1	Rear tailgate	\$ 1,399.70	✓
6	1	Rear tailgate "NISSAN" emblem	\$ 125.60	✓
7	1	RH taillamp bracket	\$ 57.40	✓
8	1	RH taillamp	\$ 148.70	✓
9	1	Rear number plate bracket	\$ 48.50	X
10	1	Rear deck end panel	\$ 848.60	✓
			\$ 5,511.60	
			Less 10%	\$ 551.16
Total :			\$ 4,960.44	

		Special Nett Items	Price	Notes
11	1 set	Rear RH side gate company sticker set	\$ 350.00	X
12	1	Rear tailgate inner metal protection panel	\$ 450.00	300in
13	1	Rear tailgate LH "70km/h" sticker	\$ 15.00	125in
14	1	Rear tailgate RH "13pax" sticker	\$ 15.00	125in
15	1	Rear number plate	\$ 45.00	X
16	1 set	Reverse sensor	\$ 280.00	X
Total :			\$ 1,155.00	

		Labour	Price	Notes
1		Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,000.00	700
2		To putty and spray Spray Paintings charges.	\$ 1,000.00	600
3		To check wirings & lightings.	\$ 40.00	200
4		To replace & re-install reverse sensors.	\$ 80.00	300
5		To supply and apply anti rust treatment	\$ 80.00	600
Total :			\$ 2,200.00	

Total Parts and Labour : \$ 8,315.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____