

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>de /</i>	1	\$	2,251.00	1800.80
2	FRONT BUMPER FIXING PARTS <i>Xnn</i>	1	\$	407.00	
3	FRONT BUMPER SECURING STRIP <i>? xnn</i>	2	\$	71.00	
4	FRONT BUMPER LOWER GRILLE-CENTRE <i>? xnn</i>	1	\$	194.00	
5	FRONT BUMPER CLOSING ELEMENT- LOWER CENTRE <i>? xnn</i>	1	\$	228.00	
6	FRONT BUMPER SPOILER <i>sch /</i>	1	\$	535.00	428
7	FRONT AIR DUCT LH <i>? xnn</i>	1	\$	63.00	
8	FRONT AIR DUCT RH <i>? xnn</i>	1	\$	63.00	
9	FRONT RADIATOR GRILLE <i>cm /</i>	1	\$	2,326.00	1860.80
10	FRONT MOUNT BRACKET LH <i>? xnn</i>	1	\$	51.00	
11	FRONT MOUNT BRACKET RH <i>? xnn</i>	1	\$	51.00	
12	FRONT COVER FOR RADIATOR GRILLE UPPER <i>? xnn</i>	1	\$	189.00	
13	FRONT OUTER AIR GUIDE GRILLE LH <i>? xnn</i>	1	\$	474.00	
14	FRONT OUTER AIR GUIDE GRILLE RH <i>? xnn</i>	1	\$	474.00	
15	FRONT OUTER SENSOR <i>? xnn</i>	2		TBC	
16	FRONT INNER SENSOR <i>? xnn</i>	2		TBC	
17	INNER PARK SEAL SENSOR <i>? xnn</i>	4	\$	14.00	
18	FRONT BUMPER CARRIER <i>? xnn</i>	1	\$	845.00	
19	FRONT BUMPER CARRIER FOAM FILLER PIECE <i>de /</i>	1	\$	124.00	97.20
20	FRONT BUMPER COVER SIGHT SHEILD <i>? cm /</i>	1	\$	127.00	101.60
SUB TOTAL SPARE PARTS		:	\$	8,487.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER GUIDE SECTION LH ? xan	1	\$ 36.00	
22	FRONT BUMPER GUIDE SECTION RH ? xan	1	\$ 36.00	
23	FRONT BUMPER BRACKET LH ? xan	1	\$ 214.00	
24	FRONT BUMPER BRACKET RH ? xan	1	\$ 214.00	
25	CAUTION LABEL ? ne /	1	\$ 14.00	10.88
26	AIRCON LABEL ? ne /	1	\$ 8.00	5.68
27	FRONT CARRIER BRACKET ? ca /	1	\$ 137.00	109.60
28	FRONT BUMPER SUPPORT BRACKET LH ? xan	1	\$ 29.00	
29	FRONT BUMPER SUPPORT BRACKET RH ? xan	1	\$ 29.00	
30	HIGH TONE HORN LH ? xan	1	\$ 126.00	
31	HIGH TONE HORN RH ? xan	1	\$ 126.00	
32	SPRING SHACKLE LH ? xan	1	\$ 29.00	
33	SPRING SHACKLE RH ? xan	1	\$ 29.00	
34	FRONT BONNET bui /	1	\$ 3,312.00	2649.60
35	FRONT BUMPER RETAINING CLIP ne /	3	\$ 3.30	2.64
36	FRONT BUMPER SAFETY CATCH NUT ne /	6	\$ 24.00	19.20
37	FRONT BONNET ATTACHMENT PARTS ne /	1	\$ 123.00	98.40
38	FRONT BONNET LID HIDGE LH/RH ? xan	1	\$ 419.00	
39	FRONT BONNET LID HIDGE RH ? xan	1	\$ 419.00	
40	FRONT BUMPER PROTECTION PAD CENTRE ne /	1	\$ 28.00	21.84
SUB TOTAL SPARE PARTS		:	\$ 5,355.30	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT BUMPER PROTECTION PAD LH <i>neu</i>	1	\$ 28.00	<i>22.00</i>
42	FRONT BUMPER PROTECTION PAD RH <i>neu</i>	1	\$ 28.00	<i>21.84</i>
43	FRONT BONNET INSULATION PAD <i>? xan</i>	1	\$ 343.00	
44	FRONT BONNET STRUT <i>? xan</i>	2	\$ 241.00	
45	FRONT BONNET SAFETY CATCH LH <i>? xan</i>	1	\$ 50.00	
46	FRONT BONNET SAFETY CATCH RH <i>? xan</i>	1	\$ 50.00	
47	FRONT BONNET LID LOCK <i>? xan</i>	1	\$ 427.00	
48	FRONT BONNET BOWDEN CABLE CENTRE <i>? xan</i>	1	\$ 58.00	
49	FRONT BONNET CABLE COVER <i>? xan</i>	1	\$ 10.00	
50	FRONT BONNET RELEASE CABLE <i>? xan cut</i>	1	\$ 58.00	<i>46</i>
51	FRONT BONNET RELEASE CABLE HANDLE <i>? xan</i>	1	\$ 13.00	
52	LID LOCK CABLE RH <i>? xan</i>	1	\$ 74.00	
53	FRONT BUMPER PLENUM CHAMBER COVER <i>? xan</i>	1	\$ 97.00	
54	FRONT LED HEADLIGHT LH <i>? xan</i>	1	\$ 7,902.00	
55	FRONT LED HEADLIGHT RH <i>can</i>	1	\$ 7,902.00	<i>6321.60</i>
56	PRESSURE CYLINDER LH <i>? xan</i>	1	\$ 198.00	
57	PRESSURE CYLINDER RH <i>? xan</i>	1	\$ 198.00	
58	HEADLIGHT WASHER HOSE <i>? xan</i>	1	\$ 86.00	
59	LOCK CARRIER MOUNTING FOR COOLANT RADIATOR <i>? xan</i>	1	\$ 1,016.00	
60	RADIATOR SUPPORT BRACKET <i>? xan</i>	2	\$ 76.00	
SUB TOTAL SPARE PARTS		:	\$ 18,855.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	A/C CONDENSER ? <i>Xnn</i>	1	\$ 622.00	
62	RADIATOR PRESSURE SENSOR ? <i>Xnn</i>	1	\$ 191.00	
63	HIGH PRESSURE VALVE SWITCH ? <i>Xnn</i>	1	\$ 51.00	
64	TEMP SENSOR BACKET ? <i>Xnn</i>	1	\$ 19.00	
65	INTER AIR COOLER ? <i>Xnn</i>	1	\$ 586.00	
66	READY MIX COOLANT 1.5 LITRE ? <i>Xnn</i>	4	\$ 95.00	
67	RADIATOR ? <i>Xnn</i>	1	\$ 904.00	
68	OUTER AIR DUCT LH ? <i>Xnn</i>	1	\$ 32.00	
69	OUTER AIR DUCT RH ? <i>coa</i>	1	\$ 31.00	24.64
70	RADIATOR AIR GUIDE LH ? <i>coa</i>	1	\$ 16.00	12.80
71	RADIATOR AIR GUIDE RH ? <i>coa</i>	1	\$ 16.00	12.80
72	RADIATOR AIR GUIDE CENTRE ? <i>Xnn</i>	1	\$ 16.00	
73	RADIATOR GUIDE LOWER ? <i>coa</i>	1	\$ 22.00	17.20
74	ENGINE AIR INTAKE HOSE ? <i>Xnn</i>	1	\$ 22.00	
75	AIR GUIDE ? <i>coa</i>	1	\$ 53.00	42.40
76	AIR FILTER ? <i>Xnn</i>	1	\$ 386.00	
77	INTAKE HOSE ? <i>Xnn</i>	1	\$ 95.00	
78	AIR MASS METER ? <i>Xnn</i>	1	\$ 567.00	
79	FRONT FENDER WING LH <i>Xnn</i>	1	\$ 1,060.00	
80	FRONT FENDER WING RH <i>Xnn</i>	1	\$ 1,060.00	
SUB TOTAL SPARE PARTS		:	\$ 5,844.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	FRONT FENDER ATTACHMENT PARTS X n n	1	\$ 53.00	
82	FRONT FENDER END PLATE LH X n n	1	\$ 74.00	
83	FRONT FENDER END PLATE RH X n n	1	\$ 74.00	
84	FRONT FENDER BRACKET LH X n n	1	\$ 35.00	
85	FRONT FENDER BRACKET RH X n n	1	\$ 35.00	
86	FRONT FENDER BRACE LH X n n	1	\$ 118.00	
87	FRONT FENDER BRACE RH X n n	1	\$ 118.00	
88	FRONT FENDER NAME PLATE LH X n n	1	\$ 164.00	
89	FRONT FENDER NAME PLATE RH X n n	1	\$ 164.00	
90	FRONT FENDER WHEEL SPOILER LH X n n	1	\$ 73.00	
91	FRONT FENDER WHEEL SPOILER RH X n n	1	\$ 73.00	
92	FRONT FENDER LINER EXTENSION LH X n n	1	\$ 35.00	
93	FRONT FENDER LINER EXTENSION RH X n n	1	\$ 36.00	
94	FRONT FENDER STONE CHIP GUARD LH X n n	1	\$ 51.00	
95	FRONT FENDER STONE CHIP GUARD RH X n n	1	\$ 51.00	
96	FRONT NUMBER PLATE SER /	1	\$ 60.00	✓
97	SUNDRIES ? n n /	1	\$ 350.00	41.12
TOTAL SPARE PARTS		:	\$ 40,105.30	
TOTAL LABOUR CHARGES		:	\$ 14,652.00	
GRAND TOTAL		:	\$ 54,757.30	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: *Pxam - Hp 90010068*
: *22/02/21 @ 1010*
:
: *6 days*
: *EXCESS: TBA*

*Revers
Resury before paint*

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 1802 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$ 1,400.00 ? x 111	
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$ 280.00 X	
4	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES	S/N \$ 800.00 250	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 6,400.00 1000	
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND RHS FRONT DOOR.	\$ 5,100.00 1100	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: \$ 14,652.00	