

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0173/2021/HR
DATE : 20-Feb-21
WIP : 16112

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/2/21

YOUR INSURED VEH NO : N/A

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul,

8 days - ok - Jy - 21 Apr 21

OWNER'S NAME : KOH BOON HOW
ADDRESS : 15 BARTLEY ROAD
#04-28
SINGAPORE 539766
TELEPHONE : HP +65 97580738
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700073271-03
VEHICLE NO : **SLL 1802 R**
MODEL CODE : A5 SPORTSBACK 2.0 TFS
MODEL YEAR : 16/11/2017
ENGINE NO : CVK 047056
CHASSIS NO : WAUZZZF50JA034274
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Feb-21
PLACE OF ACCIDENT : BUGIS, SINGAPORE. VICTORIA STREET
(BUGIS JUNCTION AND BUGIS VILLAGE TRAFFIC LIGHT)

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 1802 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$	1,400.00	
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$	280.00	
4	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES	S/N \$	800.00	\$ 250.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$	6,400.00	\$ 1,000.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND RHS FRONT DOOR.	\$	5,100.00	\$ 1,100.00
	<i>Supplementary</i>			\$ 1,380.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 14,652.00	\$ 4,402.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,251.00	\$	1,800.80
2	FRONT BUMPER FIXING PARTS	1	\$ 407.00		
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00		
4	FRONT BUMPER LOWER GRILLE-CENTRE	1	\$ 194.00		
5	FRONT BUMPER CLOSING ELEMENT- LOWER CENTRE	1	\$ 228.00		
6	FRONT BUMPER SPOILER	1	\$ 535.00	\$	428.00
7	FRONT AIR DUCT LH	1	\$ 63.00		
8	FRONT AIR DUCT RH	1	\$ 63.00		
9	FRONT RADIATOR GRILLE	1	\$ 2,326.00	\$	1,860.80
10	FRONT MOUNT BRACKET LH	1	\$ 51.00		
11	FRONT MOUNT BRACKET RH	1	\$ 51.00		
12	FRONT COVER FOR RADIATOR GRILLE UPPER	1	\$ 189.00		
13	FRONT OUTER AIR GUIDE GRILLE LH	1	\$ 474.00		
14	FRONT OUTER AIR GUIDE GRILLE RH	1	\$ 474.00		
15	FRONT OUTER SENSOR	2	TBC		
16	FRONT INNER SENSOR	2	TBC		
17	INNER PARK SEAL SENSOR	4	\$ 14.00		
18	FRONT BUMPER CARRIER	1	\$ 845.00		
19	FRONT BUMPER CARRIER FOAM FILLER PIECE	1	\$ 124.00	\$	99.20
20	FRONT BUMPER COVER SIGHT SHEILD	1	\$ 127.00	\$	101.60
SUB TOTAL SPARE PARTS		:	\$ 8,487.00	\$	4,290.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 4,290.40
21	FRONT BUMPER GUIDE SECTION LH	1	\$ 36.00	
22	FRONT BUMPER GUIDE SECTION RH	1	\$ 36.00	
23	FRONT BUMPER BRACKET LH	1	\$ 214.00	
24	FRONT BUMPER BRACKET RH	1	\$ 214.00	
25	CAUTION LABEL	1	\$ 14.00	\$ 10.88
26	AIRCON LABEL	1	\$ 8.00	\$ 5.68
27	FRONT CARRIER BRACKET	1	\$ 137.00	\$ 109.60
28	FRONT BUMPER SUPPORT BRACKET LH	1	\$ 29.00	
29	FRONT BUMPER SUPPORT BRACKET RH	1	\$ 29.00	
30	HIGH TONE HORN LH	1	\$ 126.00	
31	HIGH TONE HORN RH	1	\$ 126.00	
32	SPRING SHACKLE LH	1	\$ 29.00	
33	SPRING SHACKLE RH	1	\$ 29.00	
34	FRONT BONNET	1	\$ 3,312.00	\$ 2,649.60
35	FRONT BUMPER RETAINING CLIP	3	\$ 3.30	\$ 2.64
36	FRONT BUMPER SAFETY CATCH NUT	6	\$ 24.00	\$ 19.20
37	FRONT BONNET ATTACHMENT PARTS	1	\$ 123.00	\$ 98.40
38	FRONT BONNET LID HIDGE LH/RH	1	\$ 419.00	
39	FRONT BONNET LID HIDGE RH	1	\$ 419.00	
40	FRONT BUMPER PROTECTION PAD CENTRE	1	\$ 28.00	\$ 21.84
SUB TOTAL SPARE PARTS		:	\$ 5,355.30	\$ 7,208.24

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 7,208.24
41	FRONT BUMPER PROTECTION PAD LH	1	\$ 28.00	\$ 22.00
42	FRONT BUMPER PROTECTION PAD RH	1	\$ 28.00	\$ 21.84
43	FRONT BONNET INSULATION PAD	1	\$ 343.00	
44	FRONT BONNET STRUT	2	\$ 241.00	
45	FRONT BONNET SAFETY CATCH LH	1	\$ 50.00	
46	FRONT BONNET SAFETY CATCH RH	1	\$ 50.00	
47	FRONT BONNET LID LOCK	1	\$ 427.00	
48	FRONT BONNET BOWDEN CABLE CENTRE	1	\$ 58.00	
49	FRONT BONNET CABLE COVER	1	\$ 10.00	
50	FRONT BONNET RELEASE CABLE	1	\$ 58.00	\$ 46.00
51	FRONT BONNET RELEASE CABLE HANDLE	1	\$ 13.00	
52	LID LOCK CABLE RH	1	\$ 74.00	
53	FRONT BUMPER PLENUM CHAMBER COVER	1	\$ 97.00	
54	FRONT LED HEADLIGHT LH	1	\$ 7,902.00	
55	FRONT LED HEADLIGHT RH	1	\$ 7,902.00	\$ 6,321.60
56	PRESSURE CYLINDER LH	1	\$ 198.00	
57	PRESSURE CYLINDER RH	1	\$ 198.00	
58	HEADLIGHT WASHER HOSE	1	\$ 86.00	
59	LOCK CARRIER MOUNTING FOR COOLANT RADIATOR	1	\$ 1,016.00	
60	RADIATOR SUPPORT BRACKET	2	\$ 76.00	
SUB TOTAL SPARE PARTS			\$ 18,855.00	\$ 13,619.68

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 13,619.68
61	A/C CONDENSER	1	\$ 622.00	
62	RADIATOR PRESSURE SENSOR	1	\$ 191.00	
63	HIGH PRESSURE VALVE SWITCH	1	\$ 51.00	
64	TEMP SENSOR BACKET	1	\$ 19.00	
65	INTER AIR COOLER	1	\$ 586.00	
66	READY MIX COOLANT 1.5 LITRE	4	\$ 95.00	
67	RADIATOR	1	\$ 904.00	
68	OUTER AIR DUCT LH	1	\$ 32.00	
69	OUTER AIR DUCT RH	1	\$ 31.00	\$ 24.64
70	RADIATOR AIR GUIDE LH	1	\$ 16.00	\$ 12.80
71	RADIATOR AIR GUIDE RH	1	\$ 16.00	\$ 12.80
72	RADIATOR AIR GUIDE CENTRE	1	\$ 16.00	
73	RADIATOR GUIDE LOWER	1	\$ 22.00	\$ 17.20
74	ENGINE AIR INTAKE HOSE	1	\$ 22.00	
75	AIR GUIDE	1	\$ 53.00	\$ 42.40
76	AIR FILTER	1	\$ 386.00	
77	INTAKE HOSE	1	\$ 95.00	
78	AIR MASS METER	1	\$ 567.00	
79	FRONT FENDER WING LH	1	\$ 1,060.00	
80	FRONT FENDER WING RH	1	\$ 1,060.00	
SUB TOTAL SPARE PARTS		:	\$ 5,844.00	\$ 13,729.52

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 13,729.52
81	FRONT FENDER ATTACHMENT PARTS	1	\$ 53.00	
82	FRONT FENDER END PLATE LH	1	\$ 74.00	
83	FRONT FENDER END PLATE RH	1	\$ 74.00	
84	FRONT FENDER BRACKET LH	1	\$ 35.00	
85	FRONT FENDER BRACKET RH	1	\$ 35.00	
86	FRONT FENDER BRACE LH	1	\$ 118.00	
87	FRONT FENDER BRACE RH	1	\$ 118.00	
88	FRONT FENDER NAME PLATE LH	1	\$ 164.00	
89	FRONT FENDER NAME PLATE RH	1	\$ 164.00	
90	FRONT FENDER WHEEL SPOILER LH	1	\$ 73.00	
91	FRONT FENDER WHEEL SPOILER RH	1	\$ 73.00	
92	FRONT FENDER LINER EXTENSION LH	1	\$ 35.00	
93	FRONT FENDER LINER EXTENSION RH	1	\$ 36.00	
94	FRONT FENDER STONE CHIP GUARD LH	1	\$ 51.00	
95	FRONT FENDER STONE CHIP GUARD RH	1	\$ 51.00	
96	FRONT NUMBER PLATE	1	\$ 60.00	\$ 60.00
97	SUNDRIES	1	\$ 350.00	\$ 41.12
TOTAL SPARE PARTS			\$ 40,105.30	\$ 13,830.64
TOTAL LABOUR CHARGES			\$ 14,652.00	\$ 4,402.00
GRAND TOTAL			\$ 54,757.30	\$ 18,232.64

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0173/2021/HR

24-Mar-21

CHANG

1 of 1

SLL 1802 R

AUDI A5 SPORTBACK 2.0 TFSI

Quantity	Description		Unit Price	Amount
Labours				
1	TO DISMANTLE AND RINSTALL LHS FRONT DOOR PANEL TRIM. TO DISMANTLE AND REINSTALL LHS WING MIRROR ASSY.	S/N	\$ 280.00	\$ 280.00
2	TO RESPRAY LHS FRONT DOOR AND RHS A-PILLAR UPPER.		\$ 1,600.00	\$ 1,100.00
GRAND TOTAL			\$ 1,880.00	\$ 1,380.00

For Premium Automobiles Pte Ltd

 Authorised Signature