

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	958F
Vehicle No.:	SLL1802R
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Feb 2021
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	CVK047056
Chassis No.:	WAUZZZF50JA034274
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$39,561.00
Original Registration Date:	16 Nov 2017
First Registration Date:	16 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$42,386.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Nov 2027
PARF Rebate Amount:	\$31,789.00
COE Expiry Date:	15 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,414.00
COE Rebate Amount:	\$38,638.00
Total Rebate Amount:	\$70,427.00

The information contained herein is correct as at 23 Feb 2021

OK

White



mart.com/used_cars/info.php?ID=942717&DL=1091

▶ Audi A5 Sportback 2.0A TFSI S-tronic Design

Overview

Financial

Accessories

Similar

Research

Photos

Map



TAY MOTOR & CREDIT PTE LTD

Our Accreditations:



Price

\$123,800

Depreciation ?

\$15,760 /yr

[View models with similar depre](#)

Reg Date

29-Aug-2017

(6yrs 6mths 5days COE left)

Mileage

51,200 km (14.7k /yr)

Manufactured ?

2017

Road Tax ?

\$1,194 /yr

Transmission

Auto

Dereg Value ?

\$65,001 as of today (change)

OMV ?

\$39,560

COE ?

\$51,000

ARF ?

\$42,384

Engine Cap

1,984 cc

Power

140.0 kW (187 bhp)

Curb Weight ?

1,535 kg

No. of Owners ?

2

Type of Vehicle

Luxury Sedan

Features

4 Cylinders Inline 16 Valve Turbocharged, 187Bhp, Torque 320Nm, 7.5s (0-100Km/h, Top Speed 239 Km/h, 7 Speed (A) S-Tronic. [View specs of the Audi A5 Coupe \(2017-2020\)](#)

Compare



ASS. REC. BY: PamREF: CC3/A1421002474/R11f3

9586

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLL 1802Rat Workshop m/s PREMIUMof 281, MUMBAI RDInsured: AKH

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 127K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLL 1802R Yr Regn: 2017, NOVType: ☒ M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: MAHINDRA 2.0TDI S.TD c.c 1984Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 69588 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAM 2225509A 034274Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim orTyre Size: F: 255/35R19

R: _____

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 11/02/2021

Survey held at

Des. of Damages: FR / Rear / OIS / NIS / UIC / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 22/02/2021PREMIUM

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 56K

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / I.B.F. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0159/2021/HR
DATE : 20-Feb-21
WIP : 16112

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/2/21

YOUR INSURED VEH NO : N/A

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : KOH BOON HOW
ADDRESS : 15 BARTLEY ROAD
#04-28
SINGAPORE 539766
TELEPHONE : HP +65 97580738
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700073271-03
VEHICLE NO : SLL 1802 R
MODEL CODE : A5 SPORTSBACK 2.0 TFS
MODEL YEAR : 16/11/2017
ENGINE NO : CVK 047056
CHASSIS NO : WAUZZZF50JA034274
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Feb-21
PLACE OF ACCIDENT : BUGIS, SINGAPORE. VICTORIA STREET
(BUGIS JUNCTION AND BUGIS VILLAGE TRAFFIC LIGHT)

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 1802 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$ 1,400.00 ?	
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$ 280.00 X	
4	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES	S/N \$ 800.00 250	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 6,400.00 1000	
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND RHS FRONT DOOR.	\$ 5,100.00 1100	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: \$ 14,652.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de /</i>	1	\$ 2,251.00	
2	FRONT BUMPER FIXING PARTS <i>nee /</i>	1	\$ 407.00	
3	FRONT BUMPER SECURING STRIP <i>?</i>	2	\$ 71.00	
4	FRONT BUMPER LOWER GRILLE-CENTRE <i>?</i>	1	\$ 194.00	
5	FRONT BUMPER CLOSING ELEMENT- LOWER CENTRE <i>?</i>	1	\$ 228.00	
6	FRONT BUMPER SPOILER <i>sch /</i>	1	\$ 535.00	
7	FRONT AIR DUCT LH <i>?</i>	1	\$ 63.00	
8	FRONT AIR DUCT RH <i>?</i>	1	\$ 63.00	
9	FRONT RADIATOR GRILLE <i>cm /</i>	1	\$ 2,326.00	
10	FRONT MOUNT BRACKET LH <i>?</i>	1	\$ 51.00	
11	FRONT MOUNT BRACKET RH <i>?</i>	1	\$ 51.00	
12	FRONT COVER FOR RADIATOR GRILLE UPPER <i>?</i>	1	\$ 189.00	
13	FRONT OUTER AIR GUIDE GRILLE LH <i>?</i>	1	\$ 474.00	
14	FRONT OUTER AIR GUIDE GRILLE RH <i>?</i>	1	\$ 474.00	
15	FRONT OUTER SENSOR <i>?</i>	2	TBC	
16	FRONT INNER SENSOR <i>?</i>	2	TBC	
17	INNER PARK SEAL SENSOR <i>?</i>	4	\$ 14.00	
18	FRONT BUMPER CARRIER <i>?</i>	1	\$ 845.00	
19	FRONT BUMPER CARRIER FOAM FILLER PIECE <i>de /</i>	1	\$ 124.00	
20	FRONT BUMPER COVER SIGHT SHEILD <i>?</i>	1	\$ 127.00	
SUB TOTAL SPARE PARTS		:	\$ 8,487.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER GUIDE SECTION LH ?	1	\$ 36.00	
22	FRONT BUMPER GUIDE SECTION RH ?	1	\$ 36.00	
23	FRONT BUMPER BRACKET LH ?	1	\$ 214.00	
24	FRONT BUMPER BRACKET RH ?	1	\$ 214.00	
25	CAUTION LABEL ?	1	\$ 14.00	
26	AIRCON LABEL ?	1	\$ 8.00	
27	FRONT CARRIER BRACKET ?	1	\$ 137.00	
28	FRONT BUMPER SUPPORT BRACKET LH ?	1	\$ 29.00	
29	FRONT BUMPER SUPPORT BRACKET RH ?	1	\$ 29.00	
30	HIGH TONE HORN LH ?	1	\$ 126.00	
31	HIGH TONE HORN RH ?	1	\$ 126.00	
32	SPRING SHACKLE LH ?	1	\$ 29.00	
33	SPRING SHACKLE RH ?	1	\$ 29.00	
34	FRONT BONNET <i>bu</i>	1	\$ 3,312.00	
35	FRONT BUMPER RETAINING CLIP <i>re</i>	3	\$ 3.30	
36	FRONT BUMPER SAFETY CATCH NUT <i>re</i>	6	\$ 24.00	
37	FRONT BONNET ATTACHMENT PARTS <i>re</i>	1	\$ 123.00	
38	FRONT BONNET LID HIDGE LH/RH ?	1	\$ 419.00	
39	FRONT BONNET LID HIDGE RH ?	1	\$ 419.00	
40	FRONT BUMPER PROTECTION PAD CENTRE <i>re</i>	1	\$ 28.00	
SUB TOTAL SPARE PARTS		:	\$ 5,355.30	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT BUMPER PROTECTION PAD LH <i>neu</i>	1	\$ 28.00	
42	FRONT BUMPER PROTECTION PAD RH <i>neu</i>	1	\$ 28.00	
43	FRONT BONNET INSULATION PAD ?	1	\$ 343.00	
44	FRONT BONNET STRUT ?	2	\$ 241.00	
45	FRONT BONNET SAFETY CATCH LH ?	1	\$ 50.00	
46	FRONT BONNET SAFETY CATCH RH ?	1	\$ 50.00	
47	FRONT BONNET LID LOCK ?	1	\$ 427.00	
48	FRONT BONNET BOWDEN CABLE CENTRE ?	1	\$ 58.00	
49	FRONT BONNET CABLE COVER ?	1	\$ 10.00	
50	FRONT BONNET RELEASE CABLE ?	1	\$ 58.00	
51	FRONT BONNET RELEASE CABLE HANDLE ?	1	\$ 13.00	
52	LID LOCK CABLE RH ?	1	\$ 74.00	
53	FRONT BUMPER PLENUM CHAMBER COVER ?	1	\$ 97.00	
54	FRONT LED HEADLIGHT LH ?	1	\$ 7,902.00	
55	FRONT LED HEADLIGHT RH <i>neu</i>	1	\$ 7,902.00	
56	PRESSURE CYLINDER LH ?	1	\$ 198.00	
57	PRESSURE CYLINDER RH ?	1	\$ 198.00	
58	HEADLIGHT WASHER HOSE ?	1	\$ 86.00	
59	LOCK CARRIER MOUNTING FOR COOLANT RADIATOR ?	1	\$ 1,016.00	
60	RADIATOR SUPPORT BRACKET ?	2	\$ 76.00	
SUB TOTAL SPARE PARTS		:	\$ 18,855.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	A/C CONDENSER ?	1	\$ 622.00	
62	RADIATOR PRESSURE SENSOR ?	1	\$ 191.00	
63	HIGH PRESSURE VALVE SWITCH ?	1	\$ 51.00	
64	TEMP SENSOR BACKET ?	1	\$ 19.00	
65	INTER AIR COOLER ?	1	\$ 586.00	
66	READY MIX COOLANT 1.5 LITRE ?	4	\$ 95.00	
67	RADIATOR ?	1	\$ 904.00	
68	OUTER AIR DUCT LH ?	1	\$ 32.00	
69	OUTER AIR DUCT RH ?	1	\$ 31.00	
70	RADIATOR AIR GUIDE LH ?	1	\$ 16.00	
71	RADIATOR AIR GUIDE RH ?	1	\$ 16.00	
72	RADIATOR AIR GUIDE CENTRE ?	1	\$ 16.00	
73	RADIATOR GUIDE LOWER ?	1	\$ 22.00	
74	ENGINE AIR INTAKE HOSE ?	1	\$ 22.00	
75	AIR GUIDE ?	1	\$ 53.00	
76	AIR FILTER ?	1	\$ 386.00	
77	INTAKE HOSE ?	1	\$ 95.00	
78	AIR MASS METER ?	1	\$ 567.00	
79	FRONT FENDER WING LH X	1	\$ 1,060.00	
80	FRONT FENDER WING RH X	1	\$ 1,060.00	
SUB TOTAL SPARE PARTS		:	\$ 5,844.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	FRONT FENDER ATTACHMENT PARTS X	1	\$ 53.00	
82	FRONT FENDER END PLATE LH X	1	\$ 74.00	
83	FRONT FENDER END PLATE RH X	1	\$ 74.00	
84	FRONT FENDER BRACKET LH X	1	\$ 35.00	
85	FRONT FENDER BRACKET RH X	1	\$ 35.00	
86	FRONT FENDER BRACE LH X	1	\$ 118.00	
87	FRONT FENDER BRACE RH X	1	\$ 118.00	
88	FRONT FENDER NAME PLATE LH X	1	\$ 164.00	
89	FRONT FENDER NAME PLATE RH X	1	\$ 164.00	
90	FRONT FENDER WHEEL SPOILER LH X	1	\$ 73.00	
91	FRONT FENDER WHEEL SPOILER RH X	1	\$ 73.00	
92	FRONT FENDER LINER EXTENSION LH X	1	\$ 35.00	
93	FRONT FENDER LINER EXTENSION RH X	1	\$ 36.00	
94	FRONT FENDER STONE CHIP GUARD LH X	1	\$ 51.00	
95	FRONT FENDER STONE CHIP GUARD RH X	1	\$ 51.00	
96	FRONT NUMBER PLATE SER /	1	\$ 60.00	
97	SUNDRIES ?	1	\$ 350.00	
TOTAL SPARE PARTS		:	\$ 40,105.30	
TOTAL LABOUR CHARGES		:	\$ 14,652.00	
GRAND TOTAL		:	\$ 54,757.30	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Peram - 4p 90010068

: 22/02/21 @ 1010

: 6 days

: EXCESS: TBA

: Revert
Resurvey before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

420013515/K19200
ASSIGNMENT
SDB 73773
Yr Regn: 2019, 04/11
11 ory 1, Taxi 1 Prime Mover 1

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 18/02/2021 15:55 (SGT)
Date of Accident 17/02/2021 20:30 (SGT)
Exact Location of Accident Bugis, Singapore
Additional Location Information VICTORIA STREET (BUGIS JUNCTION & BUGIS VILLAGE TRAFFIC LIGHT)
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLL1802R

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner KOH BOON HOW
NRIC No SXXXX958F
Email Address KENNETH.KOH@LUYE.COM
Mobile Phone No (Phone) +65-97580738
Alternative Phone No (Office) +65-97580738

VEHICLE PARTICULARS

Manufacturer Audi
Model A5
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company AIG
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 1700073271-03
Cover Note Number -

DRIVER

Name of Driver KOH BOON HOW
NRIC No SXXXX958F
Date Of Birth 27/01/1981

Occupation Indoor
Date Of Driving Pass 22/06/2010
Driving experience 10 YEARS AND 8 MONTHS
Gender Male
Mobile Number (Phone) +65-97580738
Alt. Phone Number (Office) +65-97580738
Email Address KENNETH.KOH@LUYE.COM
Address 15 BARTLEY ROAD
Address complement #04-28
Postcode 539766
Is the driver the policyholder? Yes
If No, Relationship of the Driver with the Insured -
Does Driver Own Other Vehicles? No
Vehicle Registration Number of Other Vehicle Owned by Driver -
Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
Weather Conditions Clear
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other material or property damaged? Yes
Number of Passengers (Including Driver) 2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name KATE CAI
Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

ACCIDENT HAPPEN ON VICTORIA STREET, IN FRONT OF TRAFFIC LIGHT IN BETWEEN BUGIS STREET AND BUGIS JUNCTION. THE CAR INFRONT SUDDENLY BRAKE DUE TO TRAFFIC LIGHT TURN TO RED, MY CAR NOT IN TIME TO BRAKE TO STOP THE SUDDEN JAM BRAKE INFRONT.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLP7988C
Vehicle Manufacturer Honda
Vehicle Model Vezel
Vehicle Variant -
Vehicle Colour -

Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-