

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0173/2021/HR

24-Mar-21

CHANG

1 of 1

SLL 1802 R

AUDI A5 SPORTBACK 2.0 TFSI

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Labours

- 1 TO DISMANTLE AND REINSTALL LHS FRONT DOOR
PANEL TRIM. TO DISMANTLE AND REINSTALL
LHS WING MIRROR ASSY.

S/N 5 280.00



- 2 TO RESPRAY (LHS) FRONT DOOR AND (RHS)
A-PILLAR UPPER.

S 1,600.00

1100



GRAND TOTAL

\$ 1,880.00

For Premium Automobiles Pte Ltd


Authorised Signature

Steve (LKK)

24/3/21

add 1 repair days

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
TEL: 6306 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLL 1802 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR, CHECK ELECTRICAL FANS AND CONTROL UNIT, PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$ 1,400.00 ?	
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$ 280.00 X	
4	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES	S/N \$ 800.00 250	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 6,400.00 1000	
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND RHS FRONT DOOR.	\$ 5,100.00 1100	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		\$ 14,652.00	

◆ PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
TEL: 6396 2323 FAX: 6841 1183
EMAIL: NORAJOH@PREMIUMAUTO.COM.SG / CLAZMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>de /</i>	1	\$	2,251.00	
2	FRONT BUMPER FIXING PARTS <i>see /</i>	1	\$	407.00	
3	FRONT BUMPER SECURING STRIP <i>?</i>	2	\$	71.00	
4	FRONT BUMPER LOWER GRILLE-CENTRE <i>?</i>	1	\$	194.00	
5	FRONT BUMPER CLOSING ELEMENT- LOWER CENTRE <i>?</i>	1	\$	228.00	
6	FRONT BUMPER SPOILER <i>sch /</i>	1	\$	535.00	
7	FRONT AIR DUCT LH <i>?</i>	1	\$	63.00	
8	FRONT AIR DUCT RH <i>?</i>	1	\$	63.00	
9	FRONT RADIATOR GRILLE <i>cm /</i>	1	\$	2,326.00	
10	FRONT MOUNT BRACKET LH <i>?</i>	1	\$	51.00	
11	FRONT MOUNT BRACKET RH <i>?</i>	1	\$	51.00	
12	FRONT COVER FOR RADIATOR GRILLE UPPER <i>?</i>	1	\$	189.00	
13	FRONT OUTER AIR GUIDE GRILLE LH <i>?</i>	1	\$	474.00	
14	FRONT OUTER AIR GUIDE GRILLE RH <i>?</i>	1	\$	474.00	
15	FRONT OUTER SENSOR <i>?</i>	2		TBC	
16	FRONT INNER SENSOR <i>?</i>	2		TBC	
17	INNER PARK SEAL SENSOR <i>?</i>	4	\$	14.00	
18	FRONT BUMPER CARRIER <i>?</i>	1	\$	845.00	
19	FRONT BUMPER CARRIER FOAM FILLER PIECE <i>de /</i>	1	\$	124.00	
20	FRONT BUMPER COVER SIGHT SHEILD <i>?</i> - <i>OR</i>	1	\$	127.00	
SUB TOTAL SPARE PARTS		:	\$	8,487.00	

ALL CHARGES ARE INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (OQ) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6041 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SL1 1802 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT BUMPER GUIDE SECTION LH ?	1	\$	36.00	
22	FRONT BUMPER GUIDE SECTION RH ?	1	\$	36.00	
23	FRONT BUMPER BRACKET LH ?	1	\$	214.00	
24	FRONT BUMPER BRACKET RH ?	1	\$	214.00	
25	CAUTION LABEL ? <i>new</i>	1	\$	14.00	
26	AIRCON LABEL ? <i>new</i>	1	\$	8.00	
27	FRONT CARRIER BRACKET ? <i>OR</i>	1	\$	137.00	
28	FRONT BUMPER SUPPORT BRACKET LH ?	1	\$	29.00	
29	FRONT BUMPER SUPPORT BRACKET RH ?	1	\$	29.00	
30	HIGH TONE HORN LH ?	1	\$	126.00	
31	HIGH TONE HORN RH ?	1	\$	126.00	
32	SPRING SHACKLE LH ?	1	\$	29.00	
33	SPRING SHACKLE RH ?	1	\$	29.00	
34	FRONT BONNET <i>Bui</i>	1	\$	3,312.00	
35	FRONT BUMPER RETAINING CLIP <i>new</i>	3	\$	3.30	
36	FRONT BUMPER SAFETY CATCH NUT <i>new</i>	6	\$	24.00	
37	FRONT BONNET ATTACHMENT PARTS <i>new</i>	1	\$	123.00	
38	FRONT BONNET LID HIDGE LH/RH ?	1	\$	419.00	
39	FRONT BONNET LID HIDGE RH ?	1	\$	419.00	
40	FRONT BUMPER PROTECTION PAD CENTRE <i>new</i>	1	\$	28.00	
SUB TOTAL SPARE PARTS		:	\$	5,355.30	

ALL CHARGES ARE INCLUSIVE OF GST
 LEGEND: REMARKS (DO) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6843 1183
EMAIL: NDRA.KHAS@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	FRONT BUMPER PROTECTION PAD LH <i>NE</i>	1	\$	28.00	
42	FRONT BUMPER PROTECTION PAD RH <i>NE</i>	1	\$	28.00	
43	FRONT BONNET INSULATION PAD ?	1	\$	343.00	
44	FRONT BONNET STRUT ?	2	\$	241.00	
45	FRONT BONNET SAFETY CATCH LH ?	1	\$	50.00	
46	FRONT BONNET SAFETY CATCH RH ?	1	\$	50.00	
47	FRONT BONNET LID LOCK ?	1	\$	427.00	
48	FRONT BONNET BOWDEN CABLE CENTRE ?	1	\$	58.00	
49	FRONT BONNET CABLE COVER ?	1	\$	10.00	
50	FRONT BONNET RELEASE CABLE ?	1	\$	58.00	
51	FRONT BONNET RELEASE CABLE HANDLE ?	1	\$	13.00	
52	LID LOCK CABLE RH ?	1	\$	74.00	
53	FRONT BUMPER PLENUM CHAMBER COVER ?	1	\$	97.00	
54	FRONT LED HEADLIGHT LH ?	1	\$	7,902.00	
55	FRONT LED HEADLIGHT RH <i>sm</i>	1	\$	7,902.00	
56	PRESSURE CYLINDER LH ?	1	\$	198.00	
57	PRESSURE CYLINDER RH ?	1	\$	198.00	
58	HEADLIGHT WASHER HOSE ?	1	\$	86.00	
59	LOCK CARRIER MOUNTING FOR COOLANT RADIATOR ?	1	\$	1,016.00	
60	RADIATOR SUPPORT BRACKET ?	2	\$	76.00	
SUB TOTAL SPARE PARTS			:	\$	18,855.00

ALL CHARGES ARE INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLL 1802 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	A/C CONDENSER ?	1	\$	622.00	
62	RADIATOR PRESSURE SENSOR ?	1	\$	191.00	
63	HIGH PRESSURE VALVE SWITCH ?	1	\$	51.00	
64	TEMP SENSOR BACKET ?	1	\$	19.00	
65	INTER AIR COOLER ?	1	\$	586.00	
66	READY MIX COOLANT 1.5 LITRE ?	4	\$	95.00	
67	RADIATOR ?	1	\$	904.00	
68	OUTER AIR DUCT LH ?	1	\$	32.00	
69	OUTER AIR DUCT RH ? - OR	1	\$	31.00	
70	RADIATOR AIR GUIDE LH ? - OR	1	\$	16.00	
71	RADIATOR AIR GUIDE RH ? - OR	1	\$	16.00	
72	RADIATOR AIR GUIDE CENTRE ?	1	\$	16.00	
73	RADIATOR GUIDE LOWER ? - OR	1	\$	22.00	
74	ENGINE AIR INTAKE HOSE ?	1	\$	22.00	
75	AIR GUIDE ? - OR	1	\$	53.00	
76	AIR FILTER ?	1	\$	386.00	
77	INTAKE HOSE ?	1	\$	95.00	
78	AIR MASS METER ?	1	\$	567.00	
79	FRONT FENDER WING LH X	1	\$	1,060.00	
80	FRONT FENDER WING RH X	1	\$	1,060.00	
SUB TOTAL SPARE PARTS		:	\$	5,844.00	

ALL CHARGES ARE INCLUSIVE OF GST
LEGEND: REMARKS (O) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6364 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 511 1802 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
81	FRONT FENDER ATTACHMENT PARTS X	1	S	51.00	
82	FRONT FENDER END PLATE LH X	1	S	74.00	
83	FRONT FENDER END PLATE RH X	1	S	74.00	
84	FRONT FENDER BRACKET LH X	1	S	35.00	
85	FRONT FENDER BRACKET RH X	1	S	35.00	
86	FRONT FENDER BRACE LH X	1	S	118.00	
87	FRONT FENDER BRACE RH X	1	S	118.00	
88	FRONT FENDER NAME PLATE LH X	1	S	164.00	
89	FRONT FENDER NAME PLATE RH X	1	S	164.00	
90	FRONT FENDER WHEEL SPOILER LH X	1	S	73.00	
91	FRONT FENDER WHEEL SPOILER RH X	1	S	73.00	
92	FRONT FENDER LINER EXTENSION LH X	1	S	35.00	
93	FRONT FENDER LINER EXTENSION RH X	1	S	36.00	
94	FRONT FENDER STONE CHIP GUARD LH X	1	S	51.00	
95	FRONT FENDER STONE CHIP GUARD RH X	1	S	51.00	
96	FRONT NUMBER PLATE SEE /	1	S	60.00	
97	SUNDRIES ?	1	S	350.00	
TOTAL SPARE PARTS		:	S	40,105.30	
TOTAL LABOUR CHARGES		:	S	14,652.00	
GRAND TOTAL		:	S	54,757.30	

ALL CHARGES ARE INCLUSIVE OF GST
 LEGEND: REMARKS (O) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.