

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF680K**AAD2102-080**

Not Notified
Paying B4 point
@ 1775.08

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHF680K

JTDKB3FUX03092232

TOYOTA

PRIUS GEN 4

16/02/2021

16/10/2020

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH

LIST

\$	<i>Bul / M</i>	485.60	<i>✓</i>
\$	<i>R</i>	332.70	<i>X</i>
\$	<i>Roller</i>	374.50	<i>✓</i>
\$	<i>RL</i>	118.30	<i>X</i>
\$	<i>RL</i>	132.60	<i>X</i>
\$	<i>RL</i>	339.60	<i>X</i>
\$	<i>RL</i>	261.00	<i>X</i>

TOTAL \$ 2,044.30**25% \$ 511.08****\$ 1,533.23****Special Nett**

- 1 REAR BUMPER SIDE CLIP
- 1 REAR FENDER LINER CLIP
- 1 TAIL LAMP CLIP
- 1SET PARKING AID
- 1SET REAR BUMPER CLIP *nec*
- 1 REAR BUMPER RETAINER CLIP

\$	<i>nn</i>	60.00	<i>X</i>
\$	<i>nn</i>	65.00	<i>X</i>
\$	<i>nn</i>	70.00	<i>X</i>
\$	<i>RL</i>	700.00	<i>X</i>
\$	<i>nn</i>	85.00	<i>50/nn</i>
\$	<i>nn</i>	75.00	<i>X</i>

TOTAL \$ 1,055.00**TOTAL PARTS \$ 2,588.23****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 240.00 *X*

AAD2102-080

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF680K

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>200</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i> 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>220</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>50</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>10</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
TOTAL	\$	5,100.00	
Over All Total	\$	7,688.23	

(PART-BY-PART) Repair Days

10 Days

2 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer