COMFORTDELGRO

Our Job Ref No : 305455002

Date		:	24/02/21	ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156					
FINA	LIZAT	ION FORM			rax: 60	040 8100			
То			LKK	Fax :					
Attn			GUO QIANG						
Vehic	cle Reg	No. : SHA	8238D		_	20/02/2021			
The	survey	and estimates of	the repairs of the above-me	ntioned vehicle	e are as follows:-				
Z	The repair job shall bill to:			NTUC		FBQ8174R			
2.	The f	finalized amount	shall be:						
	(a)	Spare Parts aft	er List discount						
	(b)	Labour Charge	s						
		Total for Part-	By-Part Repair Cost						
	(c.)		air (if applicable) sum repair cost after Less: m Repair cost	-	=	\$1,700.00			
3. 4.	Estimated normal period for repairs: 2 working days. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days								
5.	Than	k you for your as	sistance.		e confirm the est alized amount	timates and			
	Signa	iture:	11	Signature:					
	Name : CHIANG Tel : 62148314			Name :					
	Fax	: <u>6546815</u>	6	-0					
For O	fficial	Use Only							
		Item Amount		Document Attached Yes or No	Confirm By (Signature)	Remarks			
Rental Rate P/Day				YES					
2. Lo:	ss of Ir	ncome Paid		N					
3. Su	rvey F	ees	_						
5. Me	dical F	ch Fee ees (on behalf if applicable)	\$7.49/\$2.00						
	errun								

emarks:				
-				

CITYCAB PTE L'

REPAIR ESTIMATE*

VEHICLE NO

SHA8238D

MAKE

MODEL

HYU-140

16/02/21

CHIANG/EROON THE

MODEL	1110-140		CHIANG /		-			
Qty	Parts Description/ Labour	Type	Unit Price	Amount				
	1 REAR BUMPER COVER / Le			\$1,106.00				
	2 REAR BUMPER BRACKET SIDE /LH /	1		\$35.60				
	10 REAR BUMPER CLIPS / NCC		\$2.20	\$22.00	opin .			
	1 REAR BUMPER UNDER COVER X CAN		-	\$228.00				
	1 REAR BUMPER UNDER COVER X 1 REAR BUMPER REINFORCEMENT X 2	1292	40	\$394.80				
	1 REAR BUMPER REFLECTOR LH	10.12		\$32.00	¥			
	1 REAR TAIL LAMP LH / CPA	or Oh	M.Sc	\$1,052.20	697,81			
	4,	12		\$2,870.60				
	20.00%	. ~ .)	77)	\$574.12				
j Pi	DISCOUNTED TOTAL	1714.	110	\$2,296.48				
1	1 REAR BUMPER ADVERTISEMENT	20		\$50.00				
)	1 REVERSE SENSOR ?			\$135.70				
				\$172.13				
	Labour Charge				0.0			
	Panel Beating			\$700.00	280			
	Spray Painting Charge			\$600.00	250			
	Check lighting			\$50.00	30			
	Remove/refix reverse sensor			\$60.00				
	Tuff Kote	600.	no	\$60.00	XM			
	TOTAL LABOUR	OAN.	40	\$1,470.00				
			wq					
	ESTIMATE TOTAL	2164	.12	\$3,938.61				
		·	,					
				1700				
9	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will							
	be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.							

2 Days. L/S After moir phos Gua Qial 2/2/2/

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" besis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: