



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 2227U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR LH	TO REPAIR SEE LABOUR	1,789.90	-
1	REAR DOOR GLASS LH	SCRATCHED	190.20	190.20
	LESS 20% DISCOUNT		-396.02	-38.04
			1,584.08	152.16
<u>NETT ITEMS</u>				
1	REAR DOOR APPS LH (N)	NECESSARY	80.00	80.00
1	FUEL TANK LID (PETROL ONLY) (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-11.00	-11.00
			99.00	99.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR DOOR LH.		800.00	350.00
	SPRAYPAINT-REAR FENDER LH ETC.		600.00	500.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	40.00	-
	TRANSFER OF DOOR & 1/4 GLASS	NOT NECESSARY	120.00	-
			1,560.00	850.00
GRAND TOTAL			3,243.08	1,101.16
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,101.16

Report Ref No. NS/INC21002483/Gqf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.