

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLL9690T**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 22.02.21
 TIME OF ACCIDENT : 07:55HRS

2	FRONT BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT RADIATOR GRILLE CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20
4	FRONT FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	BONNET LOCK BRACE PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
6	BONNET INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	FRONT SUPPORT PANEL SEALANT <i>new</i>	1	\$ 100.00	\$ 100.00	+
8	RADIATOR TOP COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
9	RADIATOR COOLANT <i>new</i>	1	\$ 60.00	\$ 60.00	40
10	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00	+
11	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
12	BOOT LID INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
13	TAILLAMP CLIPS (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	10
14	TAILLAMP PANEL SEALANT RH <i>new</i>	1	\$ 60.00	\$ 60.00	+
15	REAR FENDER SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00	50
16	REAR FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	40
17	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
18	REAR WINDSCREEN SEALANT <i>3 year</i>	1	\$ 80.00	\$ 80.00	40
19	REAR WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	40
20	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
21	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
22	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 350.00	\$ 350.00	+
23	BREAKDOWN TRIANGLE SIGN <i>new</i>	1	\$ 180.00	\$ 180.00	+
24	REVERSE SENSOR (SET) <i>Missing</i>	1	\$ 220.00	\$ 220.00	20
25	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	+

TOTAL \$ 2,870.00

610

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	600
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	400
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
5	REFOCUS HEADLAMP BEAM	\$ 60.00	30

1150

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLL9690T**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 22.02.21
 TIME OF ACCIDENT : 07:55HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	1300
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1300
3	TUFF COAT	\$ 250.00	100
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	80
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
8	Remove and Refit Rear Windscreen	\$ 250.00	X 120
9	TRANSFER BOOTLID MECHANISM	\$ 80.00	✓
10	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
11	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 80.00	X
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	80
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	X

TOTAL \$ 8,570.00

TOTAL PARTS COST : \$ 26,189.15
 TOTAL LABOUR COST : \$ 8,570.00
 TOTAL REPAIR COST : \$ 34,759.15

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF THE REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY

MICHELLE

SERVICE ADVISOR
 MICHELLE (HP:98564815)

LKK Auto Consultants hence notify the Repairer before extra spray painting
 To resurvey before extra spray painting
 To display damaged part(s) during resurvey
 Part prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Knowledge by Repairer

Adrian King.
 1/s 23/02/21

14 Days.

total: 16830.07

1/s: 13.4C

13.4C

3190

2770