

Hill Hsingway

not allowed  
max 5  
1/5 \$ 6000 | 7 days



**ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road, Eunos Spring  
#08-1339 Singapore 470130  
Tel: 9450 7920  
✉ zoomautowerks@gmail.com

Car Number: SLE3489K

Model : Mitsubishi Attrage

Damaged Area: (Rear Portion)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

**Parts / Material :**

1	Rear Bumper	DD/Re 748	\$ 758.40	/
2	Rear Bumper Side Retainer @ 65.00	11	\$ 130.00	X
3	Rear Bumper Bracket @ 78.00	11	\$ 156.00	X
4	Rear Bumper Clips	ner 50	\$ 60.00	/
5	Rear Bootlid Panel	ro/ser 791	\$ 876.50	/
6	Rear Bootlid Chrome Moulding	one 285	\$ 318.50	/
7	Rear Bootlid Inner Lock	ser 218	\$ 286.40	/
8	Rear Bootlid Catch	11	\$ 38.70	X
9	Rear Bootlid Logo	ner 69	\$ 98.20	/
10	Rear Bootlid Name Plate (Mivec)	ner 25	\$ 78.40	/
11	Rear Bootlid Name Plate (Attrage)	ner 21	\$ 95.60	/
12	Rear Bootlid Weather Strip	twi 157	\$ 210.50	/
13	Rear Bootlid Keyless Sensor	one 9100	\$ 286.20	/
14	Rear Taillamps @ 685.40	one 335x2=670	\$ 1,370.80	/
15	Rear Taillamp Panel @ SGD 310.00	R	\$ 620.00	X
16	Rear End Panel	body 425	\$ 825.40	/
17	Rear End Panel Top Garnish	twi 148	\$ 215.80	/
18	Rear End Panel Top Garnish Clips	11	\$ 60.00	X
19	Rear Fender @ SGD 786.00	R	\$ 1,572.00	X
20	Rear Fender Inner Trim Garnish @ 385.70	N/ser 242	\$ 771.40	IPC
21	Rear Fender Inner Trim Garnish Clips	11	\$ 80.00	X
22	Rear Fender Inner Shield @ 196.50	11	\$ 352.00	X
23	Rear Fender Inner Shield Clips	11	\$ 80.00	X
24	Rear Spare Tyre Top board	twi 255	\$ 265.40	/
25	Rear Spare Tyre Top Foam @ 325.60	11	\$ 651.20	X
26	Rear Spare Tyre Panel	R	\$ 980.00	X

Parts : \$ 11,237.40  
 Less Parts 10% : \$ 1,061.74  
**Total Parts : \$ 9,555.66**

**Special Net Items :**

Rear Taillamp Panel Sealant	11	\$ 60.00	X
Rear Windscreen Glass Sealant	11	\$ 80.00	X
Rear End Panel Sealant	ner	\$ 80.00	50
Rear Spare Tyre Panel Sealant	11	\$ 80.00	X
Rear Bumper Lower Spoiler (Accessories)	one	\$ 850.00	/
Rear Exhaust Muffler Chrome @ 255.00	11	\$ 510.00	X
Rear Number Plate W/Base Garnish	one	\$ 80.00	X

1 set Reverse Sensor

\$ 280.00 200

Total S/N Parts : \$ 2,020.00

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas	\$ 1,400.00	1100
To Putty, Spray Paint on Affected Accident Areas	\$ 1,600.00	1260
To Check & Re-Connect all electrical wiring	\$ 50.00	20
To Remove & Install Rear Windscreen Glass	u1 \$ 150.00	X
To Remove & Install Rear Bootlid Components Trim & Garnish	\$ 150.00	60
To Remove & Install Rear Fenders Trim, Garnish	\$ 150.00	80
To Re-position & Align Reverse Sensor	\$ 120.00	50
To Conduct Water Leakage Test	u1 \$ 150.00	X
To Rust Proof Affected Areas	\$ 200.00	80
<b>Total Labour :</b>	<b>\$ 3,970.00</b>	

TOTAL PARTS :	\$ 9,555.66
TOTAL SPECIAL NET ITEM :	\$ 2,020.00
TOTAL LABOUR :	\$ 3,970.00
<b>TOTAL REPAIR COST :</b>	<b>\$ 15,545.66</b>

DATE OF SURVEY / INSPECTED:  
 RECOMMENDED PART BY PART / LUMP SUM :  
 RECOMMENDED NUMBER OF DAYS :  
 SURVEY BY / SURVEYOR FIRM :  
 RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :  
 FINALISED AMOUNT :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

P-4195  
 102  
 P-3775.50  
 S/N-1100  
 L-2660  
 7575.50  
 202  
 6020