

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0158/2021/HR
DATE : 19-Feb-21
WIP : 15869

Xiao Chun.

14409.12

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/2/21

YOUR INSURED VEH NO : N/A

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : ZHANG HONGMEI
ADDRESS : 25 DUKE'S ROAD
#01-04
SINGAPORE 268906
TELEPHONE : HP +65 90691220
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800028155-02
VEHICLE NO : **SJK 6817 U**
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 19/3/2018
ENGINE NO : CVK 050358
CHASSIS NO : WAUZZZF48JA072634
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Feb-21
PLACE OF ACCIDENT : 23 DUKE'S ROAD SINGAPORE 268905

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJK 6817 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00 ✓	✓
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$ 600.00 X.	X.
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$ 400.00 X.	X.
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS	S/N \$ 200.00 150 X.	X.
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00 X.	X.
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS.	S/N \$ 1,400.00 X.	X.
7	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER.	S/N \$ 800.00 X.	X.
SUB TOTAL LABOUR CHARGES		: \$ 5,160.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJK 6817 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
8	TO PUT UP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00	X
9	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 700.00	✓ ✓
10	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR AND LHS FRONT FENDER. CUT OUT AND WELD LHS REAR FENDER, LHS SILL PANEL AND LHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. RE INSTALL ALL PARTS REMOVED.	\$ 10,500.00	2750 ✓
11	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS FRONT DOOR, LHS FRONT FENDER, FRONT BUMPER, LHS WING MIRROR COVER, DOOR HANDLES, DOOR ENTRANCES, ROOF CHANNEL, LHS SILL PANEL, LHS B-PILLAR, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORK.	\$ 8,950.00	$ \begin{array}{l} 5 \times 550 = 2750 \\ \text{Mirror} = 150 \\ \text{Handle } \times 2 = 100 \times 2 = 200 \\ \hline 3100 \checkmark \end{array} $
12	TO RENEW LHS FRONT AND LHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	S/N \$ 520.00	240 ✓
13	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 384.00	182 ✓
TOTAL LABOUR CHARGES		: \$ <u>28,614.00</u>	



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJK 6817 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER <i>Regis</i>	1	\$	2,181.00	+
2	REAR BUMPER FIXING PARTS	1		TBC	+
3	REAR BUMPER GUIDE SECTION CENTER <i>2 new</i>	1	\$	44.00	+
4	REAR BUMPER GUIDE SECTION LH / RH	2	\$	46.00	+
5	SIDE PANEL FRAME LH <i>Regis</i>	1	\$	3,034.00	+
6	REAR WINDOW <i>2 new</i>	1	\$	1,154.00	+
7	SIDE WINDOW LH	1	\$	616.00	+
8	SILL TRIM STRIP LH	1	\$	120.00	+
9	REAR WHEEL HOUSING LINER LH <i>new</i>	1	\$	240.00	+
10	REAR WHEEL HOUSING LINER ATTACHMENT PART <i>new</i>	1		TBC	+
11	REAR DOOR LH <i>Dented</i>	1	\$	3,192.00	✓ 2553.60
12	REAR DOOR OUTER SEAL LH <i>new</i>	1	\$	205.00	✓ 164
13	BONDING AGENT <i>2 new</i>	1	\$	49.00	? X
14	CLEANING SOLUTION <i>2 new</i>	1	\$	68.00	? X
15	APPLICATOR <i>2 new</i>	1	\$	8.00	? X
16	REAR DOOR SEALING STRIP LH <i>new</i>	1	\$	17.00	+
17	REAR DOOR ATTACHMENT PARTS LH <i>new</i>	1		TBC	+
18	REAR DOOR CATCH LH <i>2 new</i>	1	\$	120.00	? X
19	REAR DOOR HANDLE LH <i>Regis</i>	1	\$	88.00	x
20	REAR DOOR HANDLE TRIM LH - INNER <i>new</i>	1	\$	8.00	+
SUB TOTAL SPARE PARTS		:	\$	11,190.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJK 6817 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	REAR DOOR HANDLE LH COVER <i>new</i>	1	\$ 6.00	+	
22	FRONT DOOR LH <i>Dented</i>	1	\$ 3,192.00	+	2553.60
23	FRONT OUTER DOOR SEAL LH <i>new</i>	1	\$ 205.00	+	164
24	BONDING AGENT	1	\$ 49.00	?	X
25	CLEANING SOLUTION	1	\$ 68.00	?	X
26	APPLICATOR	1	\$ 8.00	?	X
27	FRONT DOOR ATTACHMENT <i>new</i>	1	TBC	+	
28	FRONT DOOR CATCH LH <i>new</i>	1	\$ 105.00	?	X
29	FRONT DOOR HANDLE LH <i>new</i>	1	\$ 88.00	?	X
30	FRONT DOOR HANDLE TRIM LH - INNER <i>new</i>	1	\$ 8.00	?	X
31	FRONT DOOR HANDLE LH COVER	1	\$ 6.00	?	X
32	FRONT DOOR MOUNTING BAR	1	\$ 164.00	?	X
33	FRONT WING MIRROR MOUNTING LH <i>cut</i>	1	\$ 1,089.00	+	871.20
34	FRONT WING MIRROR CAP LH <i>Regis</i>	1	\$ 289.00	+	
35	FRONT FENDER LH <i>Dented</i>	1	\$ 767.00	+	613.20
36	FRONT FENDER ATTACHMENT PARTS LH <i>new</i>	1	\$ 202.00	+	
37	FRONT FENDER BRACE LH <i>new</i>	1	\$ 118.00	?	X
38	FRONT WHEEL HOUSING LINER LH <i>new</i>	1	\$ 240.00	+	
39	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS LH <i>new</i>	1	TBC	+	
40	FRONT FENDER FLEDGE COVER LONG LH <i>new</i>	1	\$ 31.00	?	X
SUB TOTAL SPARE PARTS		:	\$ 6,635.00		

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJK 6817 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	FRONT FENDER FLEDGE COVER LH SHORT <i>Not Nec</i>	1	\$ 23.00	? X
42	FRONT WHEEL STONE CHIP GUARD <i>ut</i>	1	\$ 51.00	✓ 40.32
43	LED HEADLIGHT LH <i>He n</i>	1	\$ 7,693.00	+
44	ALUMINIUM RIM LH FRONT/REAR <i>He n</i>	2	\$ 2,284.00	+
45	ACRYLIC SEALANT	S/N	\$ 180.00	+
46	CAVITY WAX	S/N	\$ 140.00	+
47	STONE CHIP	S/N	\$ 180.00	+
48	METAL FILLER POWDER <i>He n</i>	S/N	\$ 280.00	+
49	1/4 GLASS SEALANT	S/N	\$ 100.00	+
50	REAR WS SEALANT	S/N	\$ 200.00	+
51	SUNDRIES <i>Nec.</i>		\$ 400.00	? 107.20 ✓
TOTAL SPARE PARTS		:	\$ 29,356.00	
TOTAL LABOUR CHARGES		:	\$ 28,614.00	
GRAND TOTAL		:	\$ 57,970.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian
23/02/21

1st Authorized 10 Days
H.S.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT