



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21002513/Aps3q2 Date: 05/01/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8310K	Veh. Inspected	SMH 7836M	
Policy No.	P2419138	Coverage (\$)	0.00	
Claim No.	S1M035BY	Excess (\$)	0.00	
Assign From		Assign Date	23/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GP72000694	Colour	SILVER	
Odometer	112755 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	HABILEAD	6 mm	
L/H Front Tyre	185/60 R15	HABILEAD	6 mm	
R/H Rear Tyre	185/60 R15	HABILEAD	6 mm	
L/H Rear Tyre	185/60 R15	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/02/2021	Inspection Date	03/03/2021	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	