

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3911 BEDOK INDUSTRIAL PARK E
 BEDOK NORTH AVE 4,
 #01-2008/10/12 SINGAPORE 489977
 TEL : 6441 5655 FAX : 6441 5355/6243 8121
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXX146H
 MOHAMAD KAMARULZAMAN BIN AHMAD
 BLK 262 TAMPINES STREET 21
 04-268
 SINGAPORE 520262
 TEL : FAX :
 PH : 90013565
 ATTN :

Not Authorized here
8/3/21
1/5 @ 3100
Take the order of 4 days

ESTIMATE BILL

Number : EB00005634
 Date : 23/02/2021
 Case No : AD00011621
 Vehicle No : SLV9491Z
 Chassis : KNAFX411MJ5761155
 Year of Mfr : 2017
 Policy No :
 Model : KIA CERATO K3 1.6A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BOOTLID <i>DD/Buc ✓</i>	1.0	1365.85	10	1229.27
2	BOOTLID EMBLEM <i>nee ✓</i>	1.0	28.34	10	25.51
3	BOOTLID HINGE RH <i>11X ✓</i>	1.0	61.04	10	54.94
4	BOOTLID HINGE LH <i>11X ✓</i>	1.0	61.04	10	54.94
5	BOOTLID LOGO - CERATO K3 <i>nee ✓</i>	1.0	27.20	10	24.48
6	BOOTLID REFLECTOR LH <i>BucX ✓</i>	1.0	710.54	10	639.49
7	BOOTLID INNER LOCK <i>nee ✓</i>	1.0	100.80	10	90.72
8	BOOTLID WEATHERSTRIP <i>nee ✓</i>	1.0	89.82	10	80.84
9	END PANEL <i>DD ✓</i>	1.0	291.55	10	262.40
10	END PANEL TOP GARNISH <i>nee ✓</i>	1.0	51.88	10	46.69
11	END PANEL TOP GARNISH CLIP <i>11X ✓</i>	3.0	5.00	10	13.50
12	REAR BUMPER <i>Dis ✓</i>	1.0	620.41	10	558.37
13	REAR BUMPER RETAINER RH <i>11X ✓</i>	1.0	25.44	10	22.90
14	REAR BUMPER RETAINER LH <i>11X ✓</i>	1.0	25.44	10	22.90
15	REAR BUMPER REINFORCEMENT <i>nee ✓</i>	1.0	286.12	10	257.51
16	REAR BUMPER LOWER GARNISH <i>Dis ✓</i>	1.0	312.89	10	281.60
17	REAR BUMPER REFLECTOR RH <i>11X ✓</i>	1.0	89.06	10	80.15
18	REAR BUMPER REFLECTOR LH <i>11X ✓</i>	1.0	89.06	10	80.15
19	REAR BUMPER CLIP <i>nee ✓</i>	4.0	1.50	6 10	5.40
List Price - Parts Sub Total					3,831.76
20	BOOTLID REVERSE CAMERA <i>BucX ✓</i>	1.0	580.00	0	580.00
21	REVERSE SENSOR <i>Shubb ✓</i>	1.0	280.00	0	280.00
22	REAR TYRE PANEL - REPAIR <i>R ✓</i>	1.0			
Special Nett Price - Parts Sub Total					860.00
Parts Total					4,691.76
23	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00
24	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
25	ANTI-RUST COATING	1.0	150.00	0	150.00
26	WIRING	1.0	40.00	0	40.00
27	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,140.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

7-3040.12
112
2736.10
S-N-200.00
L-1530
 Issued by : Anysia
4446.10
302
3112.

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
 BEDOK NORTH AVE 4,
 #01-2008/10/12 SINGAPORE 489977
 TEL : 6441 5655 FAX : 6441 5355/6243 8121
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXX146H
 MOHAMAD KAMARULZAMAN BIN AHMAD
 BLK 262 TAMPINES STREET 21
 04-268
 SINGAPORE 520262
 TEL : FAX :
 PH : 90013565
 ATTN :

ESTIMATE BILL

Number : EB00005634
Date : 23/02/2021
Case No : AD00011621
Vehicle No : SLV9491Z
Chassis: KNAFX411MJ5761155
Year of Mfr 2017
Policy No
Model : KIA CERATO K3 1.6A

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
	<div style="border: 1px solid blue; padding: 5px; margin: 10px auto; width: 80%;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
SINGAPORE DOLLARS : SEVEN THOUSAND THREE HUNDRED NINE AND CENTS NINETY-EIGHT ONLY			Less Excess		0.00
			SUBTOTAL		6,831.76
			GST 7.00%		478.22
			TOTAL		7,309.98

Date of accident : 17/02/2021 09:00 PM. Place : T - JUNCTION OF TAMPINES STREET 22 AND AVENUE 2

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

 CUSTOMER SIGNATURE

 AUTHORISED SIGNATURE