

TPAXA Denise.

FONG MOTORS				
1 Kaki Bukit Ave 6 #01-27/45				
AutoBay@ Kaki Bukit, Singapore 417883				
Tel: 6748 5648, Email: fongmotors@gmail.com				
Estimate of Cost of Repairs				
		Date	28-Feb-2021	
		Vehicle No.	SVJ2563U	
		Model	Toyota Wish	
		CHASSIS/ENG#	JTDGJ20W905001825	
PARTS				
S/N	Item	Quantity	Unit Price	Amount
1	Bonnet <i>Regrs</i>	1	\$868.80	\$868.80 <i>X</i>
2	Radiator Grille <i>New</i>	1	\$292.60	\$292.60 <i>X</i>
3	Top Panel Garnish <i>New</i>	1	\$86.80	\$86.80 <i>X</i>
4	Support Panel <i>Regrs</i>	1	\$1,179.50	\$1,179.50 <i>X</i>
5	Front Bumper <i>Distorted</i>	1	\$694.90	\$694.90 <i>585</i>
6	Bumper Fog Lamp Assembly <i>cracked</i>	1	\$298.60	\$298.60 <i>✓</i>
7	Bumper Side Retainer <i>New RH</i>	2	\$42.80	\$85.60 <i>42.80</i>
8	Head Lamp RH/LH <i>cracked</i>	2	\$1,080.60	\$2,161.20 <i>1344</i>
9	Radiator Spare Tank <i>Regrs</i>	1	\$163.10	\$163.10 <i>✓</i>
10	Wiper Tank <i>Defunct</i>	1	\$146.50	\$146.50 <i>✓</i>
11	Front Fender <i>Distorted</i>	1	\$875.90	\$875.90 <i>✓</i>
12	Fender Undergarnish <i>Defunct</i>	1	\$196.70	\$196.70 <i>✓</i>
13	Undercarriage Knuckle Arm <i>Defunct</i>	1	\$487.20	\$487.20 <i>✓</i>
14	Undercarriage Lower Arm <i>Bent</i>	1	\$492.80	\$492.80 <i>✓</i>
15	Undercarriage Wheelhub <i>Defunct</i>	1	\$197.90	\$197.90 <i>✓</i>
16	Undercarriage Bearing <i>Defunct</i>	1	\$139.40	\$139.40 <i>✓</i>
17	Undercarriage Shock Absorber <i>Bent</i>	1	\$429.50	\$429.50 <i>✓</i>
18	Undercarriage Steering Rack <i>New</i>	1	\$1,524.90	\$1,524.90 <i>X</i>
19	Undercarriage Cross-member <i>Bent</i>	1	\$1,758.30	\$1,758.30 <i>1,758.30</i>
20	Undercarriage Driveshaft <i>Bent</i>	1	\$1,499.80	\$1,499.80 <i>✓</i>
21	Undercarriage Linkage <i>Bent</i>	1	\$170.90	\$170.90 <i>✓</i>
22	RH Side Skirt <i>Torn</i>	1	\$1,161.70	\$1,161.70 <i>X</i>
23	Bonnet Stay-clip <i>New</i>	1	\$53.80	\$53.80 <i>X</i>
Sub-total 1				\$14,966.40
NETT ITEMS				
S/N	Item	Quantity	Unit Price	Amount
1	Bumper Clip <i>New</i>	1	\$40.00	\$40.00 <i>30</i>
2	Top Panel Garnish Clip <i>New</i>	1	\$30.00	\$30.00 <i>X</i>
3	Tyre <i>cracked</i>	1	\$280.00	\$280.00 <i>200</i>
4	Rim <i>at</i>	1	\$650.00	\$650.00 <i>500</i>
5	Fender Undergarnish Clip <i>New</i>	1	\$40.00	\$40.00 <i>30</i>
Sub-total 2				\$1,040.00
LABOUR				
1	Knocking of all affected parts			\$1,200.00 <i>800</i>
2	Computerised wheel alignment			\$250.00 <i>80</i>
3	Remove & replace undercarriage cross-member			\$550.00 <i>350</i>
5	Tuff Kote			\$150.00 <i>50</i>
6	To conduct wiring checks			\$80.00 <i>30</i>
7	Spray painting on side skirt, door, fender, bonnet, bumper and top panel			\$1,200.00 <i>1000</i>
Labour Total				\$3,430.00
Parts & Labour Total				\$19,436.40

8828.40

6621.30

SN: 680

1,758.30

639307

760

2310

total 10371.30

h/s 8.31K

07 Days

8.31K
08 Days

Acknowledged by Repairer

Signature:

Date:

Auto Consultants hence notify

the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company