


55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 4803 Z**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	/ /
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$ 1,400.00	/ /
3	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	? 250 XMM
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	3 days 500 x 4.5 to 0.5 = 5 days 5,500.00	2250 + 250 = 2500
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND FRONT FENDER.	160 @ 550 \$ 3,600.00	1260 /
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/ /
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 11,672.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 4803 Z**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>de/</i>	1	\$ 2,161.00	1728.40
2	FRONT BUMPER CLOSING ELEMENT - LH <i>? x su</i>	1	\$ 59.00	
3	FRONT BUMPER CLOSING ELEMENT - RH <i>? x su</i>	1	\$ 59.00	
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>cm/</i>	1	\$ 217.00	173.20
5	FRONT BUMPER LOWER GRILLE COVER <i>? cm/</i>	1	\$ 51.00	48.80
6	FRONT BUMPER GRILLE - LH / RH <i>? x su</i>	2	\$ 220.00	
7	FRONT BUMPER LOWER CLOSING ELEMENT <i>? cm/</i>	1	\$ 190.00	151.60
8	FRONT BUMPER SPOILER <i>cm/</i>	1	\$ 383.00	306.40
9	FRONT BUMPER SPOILER BRACKET <i>? x su</i>	1	\$ 21.00	
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>x su</i>	2	\$ 306.00	
11	RADIATOR GRILLE <i>cm/</i>	1	\$ 1,433.00	1146.40
12	RADIATOR GRILLE STRIKER PLATE <i>cm/</i>	1	\$ 244.00	194.80
13	RADIATOR GRILLE COVER CAP <i>? x su</i>	1	\$ 45.00	
14	PARKING MODULE BRACKET <i>? x su</i>	1	\$ 41.00	
15	PARKING MODULE SECURING PLATE <i>? x su</i>	1	\$ 33.00	
16	FRONT BUMPER CAMERA <i>x su</i>	1	\$ 1,141.00	
17	FRONT BUMPER REINFORCEMENT <i>bt/</i>	1	\$ 916.00	732.40
18	FRONT BUMPER REINFORCEMENT FOAM FILLER <i>? cm/</i>	1	\$ 102.00	81.60
19	FRONT BUMPER TOP COVER <i>de/</i>	1	\$ 123.00	98.00
20	FRONT BUMPER GUIDE SECTION - LH / RH <i>? x su</i>	2	\$ 78.00	
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 7,823.00</b>	

ALL CHARGES ARE INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.




55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 4803 Z**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	CAUTION STICKER <i>na/</i>	1	\$	14.00 10.88
22	AIR COND STICKER <i>na/</i>	1	\$	8.00 5.68
23	SIGNAL HORN HIGH TONE - LH ? <i>svc</i>	1	\$	137.00
24	SIGNAL HORN LOW TONE - RH ? <i>svc</i>	1	\$	130.00
25	HORN BRACKET - LH / RH ? <i>svc</i>	2	\$	44.00
26	FRONT PARKING SENSOR <i>X svc</i>	2	\$	500.00
27	FRONT PARKING SENSOR SEAL RING <i>X nn</i>	4	\$	14.00
28	FRONT FENDER - LH <i>X svc</i>	1	\$	1,286.00
29	FRONT FENDER ATTACHMENT PARTS - LH <i>X nn</i>	1	\$	63.00
30	FRONT FENDER BRACKET - LH REAR <i>X svc</i>	1	\$	88.00
31	FRONT FENDER BRACKET - LH FRONT <i>X svc</i>	1	\$	32.00
32	FRONT FENDER SEAL - LH <i>X nn</i>	1	\$	36.00
33	FRONT FENDER DAMPER - LH UPPER <i>X nn</i>	1	\$	32.00
34	FRONT WHEEL HOUSING LINER - LH FRONT <i>X svc</i>	1	\$	240.00
35	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>X nn</i>	1	\$	101.00
36	BONNET <i>bt/</i>	1	\$	3,508.00 2806.40
37	BONNET HINGE - LH / RH ? <i>bt/</i>	2	\$	146.00 115.52
38	BONNET ATTACHMENT PARTS <i>X nn</i>	1	\$	296.00
39	BONNET STRIKER - LH / RH <i>X svc</i>	2	\$	220.00
40	BONNET SOUND ABSORBER <i>de/</i>	1	\$	219.00 175.20
<b>SUB TOTAL SPARE PARTS</b>		:	\$	<b>7,114.00</b>

ALL CHARGES ARE INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.




55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 4803 Z**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET IMPACT PROTECTION <i>cellt ✓</i>	1	S	28.00 21.84
42	PLENUM CHAMBER COVER <i>sc ✓</i>	1	S	129.00 103.20
43	BONNET BOWDEN CABLE <i>? xsv ✓</i>	1	S	58.00
44	BONNET LOCK W/ MICRO SWITCH <i>? xsv ✓</i>	1	S	427.00
45	BONNET RELEASE ELEMENT <i>bt ✓</i>	1	S	58.00 46.00
46	BONNET RELEASE LEVER <i>sc ✓</i>	1	S	14.00 11.20
47	BONNET BOWDEN CABLE COVER <i>? xsv ✓</i>	1	S	10.00
48	HEADLIGHT MOUNTING - LH / RH <i>cm / xsv ✓</i>	1pc ✓	S	236.00 94.40
49	LED HEADLIGHT - LH <i>? xsv ✓</i>	1	S	5,589.00
50	LIFT CYLINDER - LH / RH <i>xsv ✓</i>	2	S	420.00
51	LIFT CYLINDER HOSE <i>xsv ✓</i>	1	S	80.00
52	FRONT LOCK CARRIER <i>cm ✓</i>	1	S	1,272.00 1017.60
53	A/C CONDENSER <i>? bt ✓</i>	1	S	551.00 440.80
54	TEMPERATURE SENSOR HOLDER <i>? fsv ✓</i>	1	S	7.00
55	ADDITIONAL RADIATOR <i>? bt ✓</i>	1	S	920.00 736.00
56	RADIATOR <i>? bt ✓</i>	1	S	1,035.00 828.00
57	READY-MIX COOLANT FLUID ( 1 LTR ) <i>cm ✓</i>	4	S	179.00 143.04
58	RADIATOR FAN <i>? xsv ✓</i>	1	S	1,529.00
59	RADIATOR AIR GUIDE - LH / RH <i>? cm ✓</i>	2	S	76.00 59.52
60	RADIATOR AIR GUIDE - UPPER / LOWER <i>cm ✓</i>	1pc ✓	S	84.00 66.08
<b>SUB TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$ 12,702.00</b>

ALL CHARGES ARE INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.




55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 4803 Z**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	FRONT WHEEL ARC COVER - LH / RH <i>new ✓</i>	2	\$ 536.00	<i>428.80</i>
62	FRONT NUMBER PLATE <i>bt ✓</i>	S/N	\$ 60.00	<i>✓</i>
63	SUNDRIES <i>? new ✓</i>		\$ 350.00	<i>5.52</i>
<b>TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 28,585.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 11,672.00</b>	
<b>GRAND TOTAL</b>		<b>:</b>	<b>\$ 40,257.00</b>	

ALL CHARGES ARE INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *RASUL - Hp 90010068*  
SURVEYED DATE : *23/03/21 @ 1530*  
AUTHORISED DATE :  
EXCESS COST : *8 - 9 days*  
LIABILITY :  
REMARKS : *EXCESS : TBA*

PLEASE NOTE : *Revert Resurvey before paint*  
THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT