

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 5964U - AIG

RIZA

Not Authorised
61 Sy @ 1300.

SHD 5964U - RIZA
 JTDGJ20W805003209
 TOYOTA
 WISH 2.0 BI-FUEL
 30.03.2015
AIG

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

LIST

		PART		
			\$	<i>Bt</i> 585.36 ✓
1	1	Front Bumper	\$	<i>Sn</i> 130.00 X
2	1	Front Bumper Lower Absorber	\$	<i>R</i> 318.11 X
3	1	Front Bumper Reinforcement	\$	<i>Dit</i> 74.50 ✓
4	1	Front Bumper Retainer RH	\$	<i>Sn</i> 74.50 X
5	1	Front Bumper Retainer LH	\$	<i>Det</i> 190.00 ✓
6	1	Front Fog Lamp Outer Chrome RH	\$	<i>Sn</i> 150.00 X
7	1	Front Bumper Fog Lamp Grille RH	\$	<i>Cit</i> 672.00 ✓
8	1	Front Headlamp RH	\$	<i>R</i> 837.60 X
9	1	Front Fender RH	\$	<i>Sn</i> 369.14 X
10	1	Front Fender Liner RH	\$	<i>Sn</i> 166.00 X
11	1	Windscreen washer tank	\$	<i>Sn</i> 462.48 X
12	1	Radiator Grille	\$	<i>R</i> 1,019.16 X
13	1	Bonnet	\$	<i>Sn</i> 115.44 X
14	1	Bonnet Centre 'TOYOTA' Logo Badge	\$	

TOTAL	\$	5,164.29
20%	\$	1,032.86
<i>25%</i>	\$	4,131.43

Special Nett

1	Front Licence Plate	\$	<i>Sn</i> 50.00 X
1 Set	Front Bumper Fastener Clip	\$	<i>Mer</i> 40.00 ✓
1	CNG Sticker	\$	<i>Mer</i> 30.00 ✓ <i>150.00</i>
1 Set	Front Fender Liner Clip	\$	<i>na</i> 40.00 X
1 Set	Rocker panel outer Garnish Clip	\$	<i>na</i> 35.00 X
1	Tyre FRT RH	\$	<i>Sn</i> 180.00 X
1	Tyre Rim FRT RH	\$	<i>Sn</i> 120.00 X
1	Front Fender Advertisement Sticker	\$	<i>na</i> 250.00 X

TOTAL	\$	745.00
-------	----	--------

TOTAL PARTS	\$	4,876.43
-------------	----	----------

Panel Beating, Knocking And Straightening
 The Necessary Portion, Remove And Renewal
 Of Parts, Adjust And Realign The same

\$

2,800.00 *200*

RIZA

TRANS-CAB AUTO SERVICES PTE LTD
NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
TEL NO.6287 6666 FAX NO.6366 8862
CO/GST REG NO.201019626G
SHD 5964U - AIG

To transfer of door fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To Rust-Proofing Of The Affected Areas.	\$	nn 220.00 X
Putty And Spray Painting Of The Affected Portion.	\$	2,700.00 200/
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To transfer of tire, rim and on wheel	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	120.00 20/

TOTAL \$ 6,780.00

Over All Total \$ 11,656.43

REPAIR DAYS

10 DAYS

1 1/2