

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LEE HUI LING
53 HUDDINGTON AVE

SINGAPORE 557623

ATTN:

Your Ref No: SLG4781Z

Claim Type: Third Party

Accident Date: 23/02/2021

TP Veh Reg No: SLP5081G

Estimate No: MC1901777
Date: 24 Feb 2021
Policy No: MT/00832833
Veh Reg No: SLG4781Z
Make/Model: MAZDA 2 5-DOOR HB
1.5L

Not Authorize

1. B.I. 1/1 Rys 8

9 days

Estimate Repair Cost to Vehicle No :SLG4781Z

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 TAILGATE	1 PC	By 956.70	✓
2 TAILGATE EMBLEM	1 PC	Me 61.20	✓
3 TAILGATE MAZDA 2 LOGO	1 PC	Me 58.30	✓
4 TAILGATE SKYACTIV TECHNOLOGY LOGO	1 PC	Me 68.00	✓
5 TAILGATE LAMP LH & RH	2 PC	466.00	?
6 TAILGATE BRACKET LH & RH	2 PC	Dr 47.00	✓
7 TAILGATE LOCK	1 PC	Me 212.30	✓
8 TAILGATE LOCK STRIKER	1 PC	25.80	?
9 TAILGATE LOCK SENSOR	1 PC	2.00	?
10 TAILGATE OPENER CONTROL (SWITCH)	1 PC	96.20	?
11 TAILGATE OPENER COVER - CHECK PRICE	1 PC	Me 0.00	✓
12 TAILGATE INNER TRIMBOARD	1 PC	93.50	?
13 TAILGATE ABSORBER LH & RH	2 PC	136.00	X
14 TAILGATE RUBBER	1 PC	Me 168.60	50/100
15 TAILAMP LH & RH	2 PC	1,528.80	?
16 TAILAMP PANEL LH & RH - CHECK PRICE	2 PC	0.00	?
17 REAR BUMPER	1 PC	By 893.40	✓
18 REAR BUMPER NO PLATE LAMP LH & RH	2 PC	111.60	2+
19 REAR BUMPER SPLASH SHIELD LH & RH	2 PC	124.60	X
20 REAR BUMPER SIDE RETAINER LH & RH	2 PC	54.40	4+
21 REAR BUMPER CLIPS	12 PC	Me 36.00	✓
22 REAR FENDER AIR VENT GRILLE LH & RH	2 PC	98.40	?
23 REAR FENDER INNER TRIMBOARD LH & RH	2 PC	423.80	4+
24 REAR END PANEL	1 PC	By 399.30	✓
25 REAR END PANEL GARNISH	1 PC	Dr 77.00	✓
26 SPARE TYRE PANEL	1 PC	By 878.70	✓
27 SPARE TYRE PANEL COVER TOP - CHECK PRICE	1 PC	0.00	✓
28 SPARE TYRE PANEL COVER BTM - CHECK PRICE	1 PC	0.00	?
29 TOOLBOX SPONGE	1 PC	Deform 195.10	✓
30 REAR WIPER MOTOR	1 PC	333.00	X
31 REAR VIEW CAMERA	1 PC	846.00	?
		8,391.70	
	Less 20%	1,678.34	6,713.36
Special Nett			
32 INNER SEAL	1 PC	Me 20.00	✓
33 WINDSCREEN SEALANT	1 PC	Me 40.00	✓



Me 111

Me 111

Me 111

Me 111

Me 111

Me 111

Me 111

Me 111

Me 111

Me 111

Me 111

Me 111

Me 111

Me 111

Me 111

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LEE HUI LING
53 HUDDINGTON AVE

SINGAPORE 557623

ATTN:

Estimate No: MC1901777
Date: 24 Feb 2021
Policy No: MT/00832833
Veh Reg No: SLG4781Z
Make/Model: MAZDA 2 5-DOOR HB
1.5L

Your Ref No: SLG4781Z
Claim Type: Third Party
Accident Date: 23/02/2021
TP Veh Reg No: SLP5081G

Estimate Repair Cost to Vehicle No :SLG4781Z

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
34 NUMBER PLATE	1 PC	35.00	✓
35 REVERSE SENSOR	1 SET	200.00	✓
		295.00	295.00
LABOUR			
36 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
37 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
38 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	1201
39 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	60.00	✓
40 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	✓
41 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	501
42 TO RESET TAILGATE	1 PC	60.00	7
43 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	✓
44 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	60.00	✓
45 TO WELD, KNOCK, REPAIR AND JACK CHASSIS TO ORIGINAL CONDITION.	1 PC	250.00	✓
46 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, SPARE TYRE PANEL. TO KNOCK & REPAIR REAR FENDER LH & RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,200.00	11001
47 TO SPRAY TAILGATE, REAR BUMPER, REAR FENDER LH & RH, END PANEL, SPARE TYRE PANEL	1 PC	1,200.00	11001
		3,350.00	3,350.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

