

ASS. REC. BY:

REF:

A/G 21002549/kb

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G 47818 Yr Regn: 09, 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Mazda 2 c.c. 1498Colour: M. Green Insured / Std / NI / NASp. Reading: 43720 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6DJ2HAA01700843Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim orTyre Size: F: 105/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

YOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 23/2/21 D.O.I. 24/2/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

/ Est not ready, may repair at 1.31 as no 2nd parts available30/6 87761-86 Carhu

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation: _____
\$ + RS. \$

Fixes

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

749F

Vehicle Details

Vehicle No.:

SLG4781Z

Vehicle to be Exported:

No

Intended Deregistration Date:

23 Feb 2021

Vehicle Make:

MAZDA

Vehicle Model:

MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT

Primary Colour:

Pink

Manufacturing Year:

2016

Engine No.:

P520356776

Chassis No.:

JM6DJ2HAA01100843

Maximum Power Output:

85.0 kW (113 bhp)

Open Market Value:

\$17,204.00

Original Registration Date:

30 Sep 2016

First Registration Date:

30 Sep 2016

Transfer Count:

0

Actual ARF Paid:

\$7,204.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

29 Sep 2026

PARF Rebate Amount:

\$5,403.00

Intended COE Rebate Details

COE Expiry Date:

29 Sep 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$50,000.00

COE Rebate Amount:

\$28,000.00

Total Rebate Amount:

\$33,403.00

The information contained herein is correct as at 23 Feb 2021

OK

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LEE HUI LING
 53 HUDDINGTON AVE

SINGAPORE 557623

ATTN:

Estimate No: MC1901777
 Date: 24 Feb 2021
 Policy No: MT/00832833
 Veh Reg No: SLG4781Z
 Make/Model: MAZDA 2 5-DOOR HB
 1.5L

Your Ref No: SLG4781Z
 Claim Type: Third Party
 Accident Date: 23/02/2021
 TP Veh Reg No: SLP5081G

Not Authorised

1. B. 1. 11 Rm 8

9 days

87761.88

Estimate Repair Cost to Vehicle No :SLG4781Z

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 TAILGATE	1 PC	By 956.70	✓
2 TAILGATE EMBLEM	1 PC	na 61.20	—
3 TAILGATE MAZDA 2 LOGO	1 PC	na 58.30	—
4 TAILGATE SKYACTIV TECHNOLOGY LOGO	1 PC	na 68.00	—
5 TAILGATE LAMP LH & RH	2 PC	sun 466.00	X
6 TAILGATE BRACKET LH & RH	2 PC	DIY 47.00	✓
7 TAILGATE LOCK	1 PC	na 212.30	✓
8 TAILGATE LOCK STRIKER	1 PC	na 25.80	X
9 TAILGATE LOCK SENSOR	1 PC	na 2.00	121.00 121.00
10 TAILGATE OPENER CONTROL (SWITCH)	1 PC	sun 96.20	X
11 TAILGATE OPENER COVER - CHECK PRICE	1 PC	na 0.00	✓ 15.00
12 TAILGATE INNER TRIMBOARD	1 PC	sun 93.50	X
13 TAILGATE ABSORBER LH & RH	2 PC	sun 136.00	X
14 TAILGATE RUBBER	1 PC	na 168.60	50/sun
15 TAILAMP LH & RH	2 PC	sun 1,528.80	X
16 TAILAMP PANEL LH & RH - CHECK PRICE	2 PC	na 0.00	X
17 REAR BUMPER	1 PC	By 893.40	✓
18 REAR BUMPER NO PLATE LAMP LH & RH	2 PC	na 111.60	✓
19 REAR BUMPER SPLASH SHIELD LH & RH	2 PC	na 124.60	✓
20 REAR BUMPER SIDE RETAINER LH & RH	2 PC	na 54.40	✓
21 REAR BUMPER CLIPS	12 PC	na 36.00	✓
22 REAR FENDER AIR VENT GRILLE LH & RH	2 PC	sun 98.40	X
23 REAR FENDER INNER TRIMBOARD LH & RH	1 PC	na 423.80	✓
24 REAR END PANEL	1 PC	By 399.30	✓
25 REAR END PANEL GARNISH	1 PC	DIY 77.00	—
26 SPARE TYRE PANEL	1 PC	na 878.70	✓
27 SPARE TYRE PANEL COVER TOP - CHECK PRICE	1 PC	na 0.00	327.80
28 SPARE TYRE PANEL COVER BTM - CHECK PRICE	1 PC	na 0.00	70.20
29 TOOLBOX SPONGE	1 PC	Defum 195.10	✓
30 REAR WIPER MOTOR	1 PC	sun 333.00	X
31 REAR VIEW CAMERA	1 PC	short 846.00	350/sun
1 bumper of bracket	cm	5.40	✓
1 1st day X2	cm	22.80	✓
Special Nett			
32 INNER SEAL	1 PC	na 20.00	✓
33 WINDSCREEN SEALANT	1 PC	na 40.00	✓
		8,391.70	
Less 20%		1,678.34	6,713.36



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LEE HUI LING
 53 HUDDINGTON AVE

SINGAPORE 557623

ATTN:

Estimate No: MC1901777
Date: 24 Feb 2021
Policy No: MT/00832833
Veh Reg No: SLG4781Z
Make/Model: MAZDA 2 5-DOOR HB
 1.5L

Your Ref No: SLG4781Z
Claim Type: Third Party
Accident Date: 23/02/2021
TP Veh Reg No: SLP5081G

Estimate Repair Cost to Vehicle No :SLG4781Z

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
34 NUMBER PLATE	1 PC	35.00	—
35 REVERSE SENSOR	1 SET	200.00	—
		295.00	295.00
LABOUR			
36 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
37 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
38 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	1201
39 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	60.00	✓
40 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	✓
41 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	501
42 TO RESET TAILGATE	1 PC	60.00	✓
43 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	✓
44 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	60.00	✓
45 TO WELD, KNOCK, REPAIR AND JACK CHASSIS TO ORIGINAL CONDITION.	1 PC	250.00	✓
46 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,SPARE TYRE PANEL.TO KNOCK & REPAIR REAR FENDER LH & RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,200.00	11001
47 TO SPRAY TAILGATE,REAR BUMPER,REAR FENDER LH & RH,END PANEL,SPARE TYRE PANEL.	1 PC	1,200.00	11001
		3,350.00	3,350.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Approved by Repairer



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LEE HUI LING
53 HUDDINGTON AVE

SINGAPORE 557623

ATTN:

Estimate No: MC1901777
Date: 24 Feb 2021
Policy No: MT/00832833
Veh Reg No: SLG4781Z
Make/Model: MAZDA 2 5-DOOR HB
1.5L

Your Ref No: SLG4781Z
Claim Type: Third Party
Accident Date: 23/02/2021
TP Veh Reg No: SLP5081G

Estimate Repair Cost to Vehicle No :SLG4781Z

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 10,358.36
		Add GST @ 7%	725.09
		Total Amount Payable	S\$ 11,083.45

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND EIGHTY THREE AND CENTS FORTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE