



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|-------------------------------------|---|--|-----------------------|
| BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883 ON BEHALF OF LIM YEN LING | | | Ref: CS/TP21002552/Uqf3e2 Date: 11/03/2021 Code: TP149 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | Veh. Inspected | SKT 3117S | |
| | Policy No. | Coverage (\$) | 0.00 | |
| | Claim No. | Excess (\$) | 0.00 | |
| | Assign From | Assign Date | 24/02/2021 | |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | MAZDA 3 (A) | c.c | 1496 |
| | Engine No. | HIDDEN | Year of Reg. | 2015 |
| | Chassis No. | JM6BM42A8G0309415 | Colour | RED |
| | Odometer | 72258 KM | Steering | AFFECTED |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 205/60 R16 | YOKOHAMA | 6 mm |
| | L/H Front Tyre | 205/60 R16 | YOKOHAMA | 6 mm |
| | R/H Rear Tyre | 205/60 R16 | YOKOHAMA | 6 mm |
| | L/H Rear Tyre | 205/60 R16 | YOKOHAMA | 6 mm |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND O/S FRONT PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| | Accident Date | 04/01/2021 | Inspection Date | 24/02/2021 |
| | Survey held at | BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883 | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 4 Working Days |