

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21002553/QTF3E2
Date: 10/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070139231
Claimant Vehicle No : SDJ23J **Insured Vehicle No :** SMV4036B
Date of Loss: 19/02/2021 Nature of Claim: TP Claim No: 5756234343SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDJ23J**
Make & Model: JAGUAR S-TYPE, 2.5 (A) Engine No: 015023360FC
Reg. Date: 07/07/1999 (Man. Year: 1999) Chassis No: SAJAC02E3XFL13699
Colour: Red Odometer: 216022 km
Engine Capacity: 2967 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/02/2021
Date Inspected: 24/02/2021 Inspected At: Jas Auto Services
60 JALAN LAM HUAT CARROS CENTRE #05-06/07
Singapore 737869
Estimated Period of Repair: 5.0 days

Adjuster: OI SUN PIN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Repair	0.00 F	*- F
2	1		*FRT RH FENDER	Crumpled	0.00 F	*- F
3	1		*REAR RH DOOR	Crumpled	0.00 F	*- F
4	1		*REAR RH DOOR GLASS REGULATOR	Crumpled	0.00 F	*- F
5	1		*REAR RH DOOR LOCK	Jammed	0.00 F	*- F
6	1		*REAR RH DOOR BOARD	Cracked	0.00 F	*- F
7	1		*REAR TOP ARM	Bent	0.00 F	*- F
8	1		*REAR LOWER ARM	Bent	0.00 F	*- F
9	1		*EXHAUST PIPE	Scratched	0.00 F	*- F
10	1		*RH ROCKER PANEL GARNISH	Deformed	0.00 F	*- F

F=Franchise part.

Total Parts (\$) **0.00** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >