

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Low

Date: 02 Mar 2021

Preliminary Advice

Insured Vehicle No	: SMT7934A	Accident Date	: 19/02/2021
TP Vehicle No	: SMH2385E	Assignment Date	: 24/02/2021
Make	: HONDA CIVIC	Est. Duration of Repair	: 4
Date of Inspection	: 24/02/2021		
Inspection At	: PKS AUTOMOTIVE PTE LTD (HQ) 8 KAKI BUKIT AVENUE 4 #01 – 52 SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,781.20
Revised Amount	:S\$	3,294.72
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,294.72
 Lump Sum Repair	 :S\$	 2,600.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :