



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11932/TEH CHIEW HWA WATSON (ZHENG QIU) Reg No/Reg Date SMP8838J / 23/08/201 Date In/Mileage / 25685 Chassis No GF7W0602070 Engine No 4J11BK3288 Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994) Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	24/02/2021/ 10:23	BLE	261 / Edwin Caina	63304			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW TAILGATE , RR BUMPER & RR END PNL REPAIR / RE-ALIGN RR FLR PNL , LHR FENDER & RHR FENDER					450 x 2	900		2700.00
E PNT98000 RESPRAY RR BUMPER , RR BUMPER BODY KIT , RR END PNL , RR FLR PNL , TAILGATE , LHR FENDER & RHR FENDER					2.5 x 350	875		2450.00
E PNT88000 REMOVE & REFIT TAILGATE COMPONENT								120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD , TRIM & CARPET								120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
E PNT88000 REMOVE & REFIT RR WINDSCREEN GLASS								240.00
M SUNDRY SUPPLY RR WINDSCREEN SEALANT								80.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING								50.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR								60.00
M SUNDRY SUPPLY REVERSE SENSOR								220.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								120.00
M SUNDRY SUPPLY BODY PNL SEALANT								80.00
M SUNDRY SUPPLY C&C BADGE								40.00
M SUNDRY Sundries								20.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11932/TEH CHIEW HWA WATSON (ZHENG QIU) Reg No/Reg Date SMP883BJ / 23/08/201 Date In/Mileage / 25685 Chassis No GF7W0602070 Engine No 4J11BK3288 Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994) Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	24/02/2021/ 10:23	BLE	261 / Edwin Caina	63304			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	FACE,RR BUMPER	✓ OK			1.00	811.00	23.00	624.47
M	BRKT,R/BMPR FACE SIDE,LH	X NM			1.00	12.00	23.00	9.24
M	BRKT,R/BMPR FACE SIDE,RH	✓ OK			1.00	12.00	23.00	9.24
M	CLIP,ENG ROOM COVER	? X NM			10.00	2.00	23.00	15.40
M	REINFORCEMENT,RR BUMPER,LH	? X NM			1.00	79.00	23.00	60.83
M	REINFORCEMENT,RR BUMPER,RH	? BT			1.00	79.00	23.00	60.83
M	EXTENSION,RR BUMPER	✓ CUT (Silver)			1.00	360.00	23.00	277.20
M	MOULDING,RR BUMPER,LH	X acc (Black) X NM			1.00	106.00	23.00	81.62
M	MOULDING,RR BUMPER,RH	✓ acc (Black)			1.00	106.00	23.00	81.62
M	REFLECTOR,TAIL LAMP,LH	X NM			1.00	100.00	23.00	77.00
M	REFLECTOR,TAIL LAMP,RH	? X NM			1.00	100.00	23.00	77.00
M	PANEL ASSY,TAILGATE	✓ OD			1.00	989.00	23.00	761.53
M	GARNISH,TAILGATE	? X NM			1.00	496.00	23.00	381.92
M	W/STRIP,TAILGATE OPENING	X NM			1.00	213.00	23.00	164.01
M	DAM,TAILGATE SIDE	✓ acc			2.00	27.00	23.00	41.58
M	FASTENER,WINDSHIELD	✓ acc			4.00	6.00	23.00	18.48
M	DAM,TAILGATE,UPR	✓ acc			1.00	13.00	23.00	10.01
M	STOPPER,WINDSHIELD GLASS	✓ acc			1.00	3.00	23.00	2.31
M	DAM,TAILGATE,LWR	✓ acc			1.00	41.00	23.00	31.57
M	LATCH,TAILGATE	X NM			1.00	477.00	23.00	367.29
M	STRIKER,TAILGATE LATCH	X NM			1.00	19.00	23.00	14.63
M	MARK,OUTLANDER	✓ acc			1.00	95.00	23.00	73.15
M	PANEL,RR END	? X NM dented			1.00	326.00	23.00	251.02
M	PANEL,RR END,INR RH	? X NM			1.00	146.00	23.00	112.42
M	TRIM,RR END	X NM			1.00	113.00	23.00	87.01
M	DECAL,MIVEC	✓ acc			1.00	36.00	23.00	27.72
M	BODY KIT, OUTLANDER	X R			1.00	1554.00	20.00	1243.20

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: 24/2/21, 10.30 am

DATE: 00- AM AUL

EXCISE - 9

SURVEYOR NAME :

Steve (LKK)

SURVEYOR SIGNATURE :

24/2/21, 10.30 am

DATE :

00- AM AL

REMARKS :

EXCISE - ?

P/P, R, BL ST
5 days

Confirm & accepted by
The Repairer of the following:
To resurvey before/after spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Nett 11,412.30
7% GST on 11412.30 798.86
Total Payable 12,211.16

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.