




Service Requests

Messages

Claims



# Service Request Details

Claim	S1M035KP
Reference	CS3/ASM21002558/Gqf3e2 
Loss Date	29 January 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	16 Mar 2021 3:19:12 PM
Request Date	16 March 2021
Due Date	
Services	Pre-Repair Survey

## Actions

Next Step    Wait for: Approve  
invoice

Add Invoice

## Vehicle Information

Incident	FBB4066A
Vehicle	
Registration #	
Make	TPVD Honda
Model	125m

## Service Address

51 Ubi Avenue 1, #01-25, , , 408933

## Primary Contact/Insured

Claim Handler

VISHNU BATHAM Shekhar

shekhar.batham@axa.com.sg

Additional Instructions      TRANSFERRED FROM S1M033MA  
CS/ASM21002558/Gqf3


Messages1   Invoices   History   **Documents**   Assessment   Metrics   Notes




Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 <a href="#">ASM_LKKInvoice_AC2103662.pdf.pdf</a>	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	25 May 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 <a href="#">LKKPreRepairInspection.pdf.pdf</a>	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	25 May 2021
 <a href="#">AXA Immediate Advice - FBB4066A (PRS).pdf.pdf</a>	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 May 2021
 <a href="#">FBB4066A Inspection Photos.pdf.pdf</a>	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	14 May 2021