

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

22/02/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP III (Grab)
Jasper

Accident date: 21/02/2021

Estimated repair cost for vehicle no: SFH9696U HONDA FREED 1.5 G A '20

CHASSIS: GB71084745

S/N	Qty	Item	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$1,460.30 1180
2	2	Rear Boot Lid Hinge <i>3 NP</i>	\$51.40	\$102.80 X
3	2	Rear Boot Lid Shock Absorber <i>3 NP</i>	\$140.00	\$280.00 X
4	1	Rear Boot Lid Emblem Logo <i>3 NP</i>		\$27.40 ✓
5	1	Rear Boot Lid Freed Logo <i>3 NP</i>		\$43.10 ✓
6	1	Rear Boot Lid Center Moulding <i>3 NP</i>		\$320.40 X
7	1	Rear Boot Lid Number Plate Lamp <i>3 NP</i>		\$34.60 X
8	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$189.50 ✓
9	1	Rear Boot Lid Inner Rubber <i>at</i>		\$120.00 ✓
10	1	Rear Boot Lid Inner Trim Board <i>at</i>		\$288.50 ✓
11	10	Rear Boot Lid Inner Trim Board Clip <i>3 NP</i>	\$6.50	\$65.00 30
12	1	Rear Boot Lid Wiper Arm <i>3 NP</i>		\$65.00 X
13	1	Rear Boot Lid Wiper Motor <i>3 NP</i>		\$137.20 ✓
14	1	Rear Boot Lid Windscreen <i>3 NP</i>		\$825.90 ✓
15	1	Rear Boot Lid Windscreen Moulding <i>3 NP</i>		\$85.30 ✓
16	2	Rear Taillamp <i>3 NP</i>	\$458.10	\$916.20 X
17	4	Rear Taillamp Clip <i>3 NP</i>	\$8.00	\$32.00 X
18	2	Rear Taillamp Panel <i>3 NP</i>	\$210.30	\$420.60 X
19	1	Rear Bumper <i>3 NP</i>		\$788.70 ✓
20	10	Rear Bumper Clip <i>3 NP</i>	\$6.50	\$65.00 30
21	2	Rear Bumper Side Retainer <i>3 NP</i>	\$16.00	\$32.00 ✓
22	2	Rear Bumper Mud Shield <i>3 NP</i>	\$36.00	\$72.00 X
23	4	Rear Bumper Mud Shield Clip <i>3 NP</i>	\$6.50	\$26.00 X
24	1	Rear Bumper Towing Cover <i>3 NP</i>		\$22.50 X
28	2	Rear Fender Inner Trim Board <i>3 NP</i>	\$327.00	\$654.00 X
29	16	Rear Fender Inner Trim Board Clip <i>3 NP</i>	\$6.50	\$104.00 X
30	1	Rear End Panel <i>Dented</i>		\$623.70 ✓
31	1	Rear End Panel Inner <i>Dented</i>		\$304.00 ✓

32	1	Rear End Panel Outer Garnish	cracked	\$104.00	✓
33	1	Rear Spare Tyre Panel	Repair	\$1,155.50	X
34	1	Rear Spare Tyre Panel Top Cover	new	\$950.00	X

3846.10

3076.96

Subtotal:- \$10,115.20

S/N	Qty	Item / Special	Nett	U/price	Amount
1	1	Rear Boot Lid Number Plate	2		\$50.00 X
2	1	Rear Boot Lid Reverse Camera	new		\$550.00 ✓
3	1	Rear Boot Lid Video Camera	new		\$680.00 X
4	2	Rear Bumper Side Reflector	LA cracked	\$200.00	\$400.00 80
5	1	Rear Bumper Reverse Sensor	new		\$380.00 20
6	1	Rear Spare Tyre Panel & End Panel Sealant	new		\$450.00 8

280

Subtotal:- \$2,510.00

Labour charges

To remove & refit cushion & trim board

\$280.00 60

To remove & refit reverse sensor

\$100.00 50

To remove & refit reverse camera

\$180.00 50

To remove & refit rear windscreen

\$120.00 ✓

Gum

\$50.00 ✓

To check wiring

\$100.00 30

Towing fee

\$100.00 X

Tuff kote

\$200.00 60

Panel beating

\$1,500.00 1000

Spray painting

\$1,200.00 800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal:- \$3,830.00

Total:- \$16,455.20

total: 5676.96

45K

C/S: 4.5K

86 Days